

Inspection Photos

API: 073-06743

Operator: K3 OIL & GAS OPERATING

Inspection Date: 3/17/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/17/2021

Inspection Photos



Photo 1. Facing east at the former access road. The fence will need to be reinstalled to the where it originally existed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/17/2021

Inspection Photos



Photo 2. . Facing east toward the location. It does not appear vegetation is establishing and there are undesirable weed debris throughout the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/17/2021

Inspection Photos



Photo 3. Center of the location facing east.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/17/2021

Inspection Photos



Photo 4. Center of the location facing north.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/17/2021

Inspection Photos



Photo 5. Center of the location facing west.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/17/2021

Inspection Photos



Photo 6. Center of the location facing south.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/17/2021

Inspection Photos



Photo 7. View of groundcover shows insufficient desirable vegetation establishment.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/17/2021

Inspection Photos



Photo 8. Facing toward the south side of the location. The vegetation shown in the photo is undesirable weeds (Russian thistle). The weeds and debris need to be controlled and removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06743 | Date: 3/17/2021