

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/23/2021

Submitted Date:

03/23/2021

Document Number:

699103278

FIELD INSPECTION FORM

Loc ID 429920 Inspector Name: Burns, Adam On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 7 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|-------------------------|---------------------------------|
| Kraich, Adam | | adam.kraich@state.co.us | |
| , | | EHSRC@bonanzacrk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|----------|--------|-------------|------------|---------|---------------------------|-------------|
| 429920 | LOCATION | AC | | | - | North Platte P-T-34HZ Pad | AC |

General Comment:

[This is an inspection on just the Archrock compressor.](#)

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | OTHER | | |
| Comment: | Oily waste on skid needs to be removed. See attached photos. | | |
| Corrective Action: | Comply with Rule 606. | Date: | 04/02/2021 |
| Type | OTHER | | |
| Comment: | Stained soil next to compressor needs to be removed. | | |
| Corrective Action: | "Properly dispose of oily waste in accordance with 905.e." | Date: | 04/02/2021 |

Overall Good:

Spills:

| Type | Area | Volume | |
|------|------|--------|--|
| | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

| | | | |
|--------------------|---|-------|-----------------|
| Type: Compressor | # 1 | | corrective date |
| Comment: | Appear to have multiple leaking valves/ fittings on both compressors causing oily waste on skid needs to be fixed or replaced. | | |
| Corrective Action: | Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. | Date: | 04/02/2021 |

Venting:

| | | | |
|--------------------|----|--|-------|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Flaring:

| | | | |
|--------------------|--|--|-------|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Inspected Facilities

Facility ID: 429920 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: AC

Corrective Action:

Date:

COGCC Comments

| Comment | User | Date |
|--|--------|------------|
| <p>COGCC Inspection Report Summary On Tuesday 3/23/21 at approximately 1146hrs, I, Inspector Adam Burns, Conducted an on-site inspection at North Platte P-T-34HZ Compressor Location of Bonanza Creek Energy, at Facility ID # 429920 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Appear to have multiple leaking valves/ fittings on both compressors causing oily waste on skid needs to be fixed or replaced. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 4/2/21. Oily waste on the compressors, needs to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 4/2/21 Stained soil next to compressor needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 4/2/21. See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | burnsa | 03/23/2021 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 699103279 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5384314 |