

Inspection Photos
Operator: Simcoe
Facility: 067-08524
Date: 3/16/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area facing southward.



Photo 3. View of the western project area from the southwestern corner facing northward. Working area is fenced. Interim reclamation areas are similar to surrounding cultivated field. Vegetation is largely dormant and appears sparse at this time.



Photo 4. View of reference area comprised of open grass field, largely dormant at this time.