

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/17/2021

Submitted Date:

03/21/2021

Document Number:

692403244

**FIELD INSPECTION FORM**

Loc ID 334585 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
		cogcc.inspections@caerusoila ndgas.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
277025	WELL	PR	12/01/2020	GW	045-10599	HMU 9-9 (9W)	RI
277026	WELL	PR	02/22/2010	GW	045-10598	ROSE RANCH FEDERAL 9 -8C (I9W)	RI
277027	WELL	PR	06/30/2009	GW	045-10597	HMU 9-8 (I9W)	RI
277028	WELL	PR	02/13/2010	GW	045-10596	ROSE RANCH FEDERAL 9 -16A (I9W)	RI
277031	WELL	PR	02/04/2014	GW	045-10593	HMU 9-16 (I9W)	RI
277032	WELL	SI	10/01/2020	GW	045-10592	HMU 10-12D (I9W)	RI
277033	WELL	PR	02/16/2010	GW	045-10591	ROSE RANCH 10-13B (I9W)	RI
277111	WELL	PR	07/01/2009	GW	045-10600	ROSE RANCH 10-13A (I9W)	RI
412879	WELL	PR	03/03/2010	GW	045-18676	ROSE RANCH 16-1B (I9W)	RI
412880	WELL	PR	02/24/2010	GW	045-18677	ROSE RANCH FEDERAL 9 -7D (I9W)	RI
412882	WELL	PR	02/19/2010	GW	045-18679	ROSE RANCH FEDERAL 10-12B (I9W)	RI

**General Comment:**

This is an Interim Reclamation & Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed remain applicable.

Inspected Facilities				
Facility ID: <u>277025</u>	Type: <u>WELL</u>	API Number: <u>045-10599</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>277026</u>	Type: <u>WELL</u>	API Number: <u>045-10598</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>277027</u>	Type: <u>WELL</u>	API Number: <u>045-10597</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>277028</u>	Type: <u>WELL</u>	API Number: <u>045-10596</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>277031</u>	Type: <u>WELL</u>	API Number: <u>045-10593</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>277032</u>	Type: <u>WELL</u>	API Number: <u>045-10592</u>	Status: <u>SI</u>	Insp. Status: <u>RI</u>
Facility ID: <u>277033</u>	Type: <u>WELL</u>	API Number: <u>045-10591</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>277111</u>	Type: <u>WELL</u>	API Number: <u>045-10600</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>412879</u>	Type: <u>WELL</u>	API Number: <u>045-18676</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>412880</u>	Type: <u>WELL</u>	API Number: <u>045-18677</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>
Facility ID: <u>412882</u>	Type: <u>WELL</u>	API Number: <u>045-18679</u>	Status: <u>PR</u>	Insp. Status: <u>RI</u>

**Reclamation - Storm Water - Pit****Interim Reclamation:**

Date Interim Reclamation Started: \_\_\_\_\_ Date Interim Reclamation Completed: \_\_\_\_\_

Land Use: \_\_\_\_\_

Comment: \_\_\_\_\_

**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002b. SOIL REMOVAL AND  
SEGREGATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002c. PROTECTION OF SOILS \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1002E. SURFACE DISTURBANCE MINIMIZATION \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003a. Waste and Debris removed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Unused or unneeded equipment onsite? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Pit, cellars, rat holes and other bores closed? Pass

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

Guy line anchors marked? \_\_\_\_\_

Comment \_\_\_\_\_

Corrective Action \_\_\_\_\_

Date \_\_\_\_\_

1003b. Area no longer in use? Pass Production areas stabilized ? \_\_\_\_\_

1003c. Compacted areas have been cross ripped? \_\_\_\_\_

1003d. Drilling pit closed? Pass Subsidence over on drill pit? Pass

Cuttings management: \_\_\_\_\_

1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? \_\_\_\_\_

Production areas have been stabilized? \_\_\_\_\_ Segregated soils have been replaced? \_\_\_\_\_

**RESTORATION AND REVEGETATION**Cropland

Top soil replaced \_\_\_\_\_ Recontoured \_\_\_\_\_ Perennial forage re-established \_\_\_\_\_

Non-Cropland

Top soil replaced \_\_\_\_\_ Recontoured Pass 80% Revegetation \_\_\_\_\_

## 1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

1003 f. Weeds Noxious weeds? \_\_\_\_\_

Comment Areas no Longer in use have been Reclaimed. Snow cover prevented detailed assessment of Interim Reclamation areas; though establishment of higher profile species of perennial vegetation are visible above snow cover. Site vegetation would need to be assessed in growing season 2021.

Corrective Action \_\_\_\_\_ Date \_\_\_\_\_

Overall Interim Reclamation

**Final Reclamation/ Abandoned Location:**

Date Final Reclamation Started: \_\_\_\_\_ Date Final Reclamation Completed: \_\_\_\_\_

Final Land Use: \_\_\_\_\_

Reminder: \_\_\_\_\_

Comment: \_\_\_\_\_

Well plugged \_\_\_\_\_ Pit mouse/rat holes, cellars backfilled \_\_\_\_\_

Debris removed \_\_\_\_\_ No disturbance /Location never built \_\_\_\_\_

Access Roads Regraded \_\_\_\_\_ Contoured \_\_\_\_\_ Culverts removed \_\_\_\_\_

Gravel removed \_\_\_\_\_

Location and associated production facilities reclaimed \_\_\_\_\_ Locations, facilities, roads, recontoured \_\_\_\_\_

Compaction alleviation \_\_\_\_\_ Dust and erosion control \_\_\_\_\_

Non cropland: Revegetated 80% \_\_\_\_\_ Cropland: perennial forage \_\_\_\_\_

Weeds present \_\_\_\_\_ Subsidence \_\_\_\_\_

## 1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% \_\_\_\_\_

TRANSECT RESULTS OF REFERENCE AREA% \_\_\_\_\_

TOTAL % OF DESIRABLE VEGETATION COVER \_\_\_\_\_

VEGETATIVE COVER \_\_\_\_\_

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date \_\_\_\_\_

Overall Final Reclamation \_\_\_\_\_ Well Release on Active Location ☐ Multi-Well Location ☐

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Degradation of pad surface has occurred in working portions of Pad. Rutting and ponding of stormwater is evident. Stabilization of Pad is needed. Refer to Photo Log attached.

Corrective Action: Install or repair required BMPs per Rule 1002.f, stabilizing pad & any other seasonal maintenance of BMPs required, by 4/30/21, or as soon as weather/ground conditions permit.

Date: 04/30/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692403257	Inspection Photos RI	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5384837">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5384837</a>