

Caerus Piceance LLC
H15
Location # 334617

Mar 23, 2021 at 10:22:12 AM
39.445580,-107.755982 ±4.78m
COGCC



location

Mar 23, 2021 at 10:22:04 AM
39.445580,-107.755982 ±4.78m
COGCC



location



Caerus Piceance LLC
H15
Location # 334617

Mar 23, 2021 at 10:22:07 AM
39.445580,-107.755982 ±4.78m
COGCC



location

Mar 23, 2021 at 10:20:21 AM
39.445370,-107.755825 ±29.68m
COGCC



location entrance / Lack of stabilization /
compaction

Caerus Piceance LLC
H15
Location # 334617

Mar 23, 2021 at 10:20:32 AM
39.445370,-107.755825 ±29.68m
COGCC



Mar 23, 2021 at 10:20:46 AM
39.445440,-107.755907 ±4.82m
COGCC



Lack of stabilization / compaction

Caerus Piceance LLC
H15
Location # 334617

Mar 23, 2021 at 10:20:50 AM
39.445440,-107.755907 ±4.82m
COGCC



Mar 23, 2021 at 10:21:06 AM
39.445440,-107.755907 ±4.82m
COGCC



Lack of stabilization / compaction

Caerus Piceance LLC
H15
Location # 334617

Mar 23, 2021 at 10:24:39 AM
39.445605,-107.755744 ±4.76m
COGCC



Mar 23, 2021 at 10:23:37 AM
39.445809,-107.755725 ±4.75m
COGCC



Lack of stabilization / compaction

Caerus Piceance LLC
H15
Location # 334617



Access road entrance from CR 319 shows signs of tracking

Caerus Piceance LLC
H15
Location # 334617

Mar 23, 2021 at 11:48:43 AM
39.449352,-107.733106 ±33.51m
COGCC



Mar 23, 2021 at 11:49:09 AM
39.449317,-107.732863 ±4.71m
COGCC



Access road entrance from CR 319 shows signs of tracking



**Caerus Piceance LLC
H15
Location # 334617**

Mar 23, 2021 at 11:49:41 AM
39.449409,-107.732909 ±4.71m
COGCC



Mar 23, 2021 at 11:49:44 AM
39.449409,-107.732909 ±4.71m
COGCC



Access road entrance from CR 319 shows signs of tracking

