

Inspection Photos
Operator: R. Bayless Producer
Facility: 067-06289
Date: 3/16/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of rutting along the access road up to 12 inches deep.



Photo 3. View of the southern fill slope facing westward from the southeastern corner.



Photo 4. View of erosional rilling within the northwestern diversion channel facing downslope.



Photo 5. View of reference area comprised of pinyon and juniper woodland with understory of shrubs such as serviceberry, mountain mahogany, antelope bitterbrush, as well as grasses and forbs such as muttongrass and penstemon.