

Inspection Photos
Operator: Hilcorp Energy
Facility: 067-08128
Date: 3/16/2021



Photo 1. View of deep rutting on the well pad up to approx. 15 inches deep. Stabilization measures need to be installed to prevent site degradation.



Photo 2. View of the southern project area facing westward. Revegetation appears to be progressing on the slope.



Photo 3. View of the northern project area from the northeastern corner facing westward. Revegetation is largely dormant with grasses such as sand dropseed and smooth brome, as well as rubber rabbitbrush.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of shrubs such as serviceberry, mountain mahogany, sagebrush, as well as grasses and forbs such as Indian ricegrass and penstemon.