

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/18/2021

Submitted Date:

03/24/2021

Document Number:

690102345

FIELD INSPECTION FORM

Loc ID 336215 Inspector Name: Maclaren, Joe On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 47120
Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP
Address: P O BOX 173779
City: DENVER State: CO Zip: 80217-

Findings:

- 2 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Canfield, Chris		chris.canfield@state.co.us	
		cogccinspections@anadarko.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
292472	WELL	TA	12/23/2019	OW	123-26364	DACONO STATE 22-36	PA
293181	WELL	TA	12/24/2019	OW	123-26490	DACONO STATE 6-36	PA
479632	SPILL OR RELEASE	AC			-	Dacono State 22-36 Flowline	EG

General Comment:

Engineering Integrity inspection performed on March 17th, 2021 in response to initial form 19 spill report Doc #402630828 received by COGCC on 03/19/2021 that outlines: During plugging and abandonment activities associated with the Dacono State 22-36 flowline, historically impacted soil was discovered at two locations along the flowline. The volume of the release is unknown.

Details of observations made during this field inspection are located in the flowline section of report. Photo uploaded.

Inspected Facilities					
Facility ID:	292472	Type:	WELL	API Number:	123-26364
Status:	TA	Insp. Status:	PA		
Facility ID:	293181	Type:	WELL	API Number:	123-26490
Status:	TA	Insp. Status:	PA		
Facility ID:	479632	Type:	SPILL OR	API Number:	-
Status:	AC	Insp. Status:	EG		

Flowline					
#1	Type: Non-Well Site	of Lines			
<u>Flowline Description</u>					
Flowline Type:	Non-Well Site	Size:	Material:		
Variance:		Age:	Contents:		
<u>Integrity Summary</u>					
Failures:		Spills:	Repairs Made:		
Coatings:		H2S:	Cathodic Protection:		
<u>Pressure Testing</u>					
Witnessed:		Test Result:	Charted:		
<u>COGCC Rules (check all that apply)</u>					
<input type="checkbox"/> 1101. Installation and Reclamation		<input type="checkbox"/> 1102. Operations, Maintenance, and Repair		<input checked="" type="checkbox"/> 1103. Abandonment	
<u>Comment:</u>	Well (Dacono State 22 -36) has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #402210855 was filed and plugging operations started on 11/19/2020. COGCC form 42 notice of flowline abandonment completed Doc #402598065 received on 02/11/2021. No flowline risers were observed at the (PA) wellhead area(s) during this field inspection. An open fenced excavation was observed approximately 1150' N-NW of the well site. Excavation and remediation activities in response to the historical release discovered appear to be in progress at this location (40.099755, -104.954467). Recent snow has filled in the excavation; no flowlines or cut ends were observed. No Anadarko or contract personnel were on site at the time of this field inspection.				Date:
Corrective Action:					

Flowline					
#1	Type: Non-Well Site	of Lines			
<u>Flowline Description</u>					
Flowline Type:	Non-Well Site	Size:	Material:		
Variance:		Age:	Contents:		
<u>Integrity Summary</u>					
Failures:		Spills:	Repairs Made:		
Coatings:		H2S:	Cathodic Protection:		
<u>Pressure Testing</u>					
Witnessed:		Test Result:	Charted:		
<u>COGCC Rules (check all that apply)</u>					
<input type="checkbox"/> 1101. Installation and Reclamation		<input type="checkbox"/> 1102. Operations, Maintenance, and Repair		<input checked="" type="checkbox"/> 1103. Abandonment	
<u>Comment:</u>	Well (Dacono State 22 -36) has been plugged and abandoned; COGCC form 42 notice of start of plugging operations Doc #402210855 was filed and plugging operations started on 11/19/2020. COGCC form 42 notice of flowline abandonment completed Doc #402598065 received on 02/11/2021. No flowline risers were observed at the (PA) wellhead area(s) during this field inspection. An open fenced excavation was observed approximately 1150' N-NW of the well site. Excavation and remediation activities in response to the historical release discovered appear to be in progress at this location (40.099755, -104.954467). Recent snow has filled in the excavation; no flowlines or cut ends were observed. No Anadarko or contract personnel were on site at the time of this field inspection.				Date:
Corrective Action:					

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102347	Well location (PA); view east	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5385174
690102348	Excavation; fence needs maintenance	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5385175