

Location

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:

corrective date

Type: Bradenhead

1

Comment: IS PLUMBED TO SURFACE

Corrective Action:

Date:

Type: Gas Meter Run

1

Comment: CAL. REPORT INDICATES GAS METER HAS BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: 217651 Type: WELL API Number: 071-06430 Status: PR Insp. Status: PR

Producing Well

Comment:

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Phone 3: THERE IS OIL IN PRIME MOVER ENGINE SKID (THIS IS THE SECOND NOTICE FOR THIS CA).

Corrective Action: COMPLY WITH THE GENERAL PROVISIONS OF THE OIL AND GAS ACT AND SB-181 CONSERNING WILDLIFE PROTECTION.

Date: 10/28/2020

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
THIS IS A FOLLOW UP TO INSP. DOC# 695103445, IT DOES NOT APPEAR THAT CA WAS ADDRESSED. NOTE THIS IS THE SECOND NOTICE FOR THIS CORRECTIVE ACTION IF CA IS NOT ADDRESSED ENFORCEMENT MAY BE CONSIDERED.	beardslt	03/24/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695104094	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5385670