

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2021

Submitted Date:

03/24/2021

Document Number:

699103290

FIELD INSPECTION FORM
 Loc ID 441121 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

18 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Kraich, Adam		adam.kraich@state.co.us	
,		EHSRC@bonanzacrk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441122	WELL	PR	01/01/2021	OW	123-41258	State Pronghorn W43-32-31MRLNC	SI
441123	WELL	PR	07/30/2015	OW	123-41259	State Pronghorn 43-32-31MRLNB	PR
441124	WELL	PR	07/01/2017	OW	123-41260	State Pronghorn X43-32-31MRLNC	PR
441125	WELL	PR	07/30/2015	OW	123-41261	State Pronghorn X44-32-31MRLNC	PR
441126	WELL	PR	07/13/2015	OW	123-41262	State Pronghorn 44-32-31MRLNB	PR
441127	WELL	PR	07/30/2015	OW	123-41263	State Pronghorn X-32-31MRLNB	PR

General Comment:

This is a follow up to FIRR #402626736. Mechanical conditions and stain soil on one well is not corrected. Rest of the CA's have been corrected.

LocationOverall Good: ☒

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Stained soil next to well needs to be removed. See attached photo.		
Corrective Action:	"Properly dispose of oily waste in accordance with 905.e."	Date:	03/15/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Other	#		corrective date
Comment:	Appears to have a leaking master valve, repair or replace. See attached photo.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 03/15/2021

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		

Corrective Action:		Date:	
--------------------	--	-------	--

Inspected Facilities

Facility ID: 441122 Type: WELL API Number: 123-41258 Status: PR Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/16/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: No annual bradenhead test on file. Submit reports.

Corrective Action: _____ Date: _____

Facility ID: 441123 Type: WELL API Number: 123-41259 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/16/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: No annual Bradenhead test on file. Submit reports.

Corrective Action: _____ Date: _____

Facility ID: 441124 Type: WELL API Number: 123-41260 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 03/16/2020 Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: No annual Bradenhead test on file. Submit reports.

Corrective Action: _____ Date: _____

Facility ID: 441125 Type: WELL API Number: 123-41261 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 03/16/2020 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0Comment: No annual Bradenhead test on file. Submit reports.

Corrective Action: _____ Date: _____

Facility ID: 441126 Type: WELL API Number: 123-41262 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 03/16/2020 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0Comment: No annual Bradenhead test on file. Submit reports.

Corrective Action: _____ Date: _____

Facility ID: 441127 Type: WELL API Number: 123-41263 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: 03/16/2020 Annual Brhd Completed? NoLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
End Surf Csg Pressure: 0Comment: No annual Bradenhead test on file. Submit reports.

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Wednesday 3/24/21 at approximately 1244hrs, I, Inspector Adam Burns, Conducted an on-site follow up inspection to FIRR #402626736 at State Pronghorn 44-32 Pad of Bonanza Creek Energy, at Location ID # 441121 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance were not corrected and observed: Stained soil next to wellhead needs to be removed. "Properly dispose of oily waste in accordance with 905.e." With a corrective action date of 3/15/21.</p> <p>Appears to be leaking Master Valve repair or replace. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 3/15/21.</p> <p>The rest of the CA's have been corrected.</p> <p>See attached photos.</p> <p>Following wells that need updated annual bradenhead test:</p> <p>State Pronghorn W43-32-31 MRLNC</p> <p>State Pronghorn 43-32-31 MRLNB</p> <p>State Pronghorn X43-32-31 MRLNC</p> <p>State Pronghorn X44-32-31 MRLNC</p> <p>State Pronghorn 44-32-31 MRLNB</p> <p>State Pronghorn X-32-31 MRLNB</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	03/24/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103291	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5385749