

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2021

Submitted Date:

03/24/2021

Document Number:

701101314

FIELD INSPECTION FORMLoc ID 335161 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10091

Name of Operator: BERRY PETROLEUM COMPANY LLC

Address: 11117 RIVER RUN BLVD

City: BAKERSFIELD State: CA Zip: 93311

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wilbourn, Don		dwilbourn@bry.com	
Armstrong, Jon		jarmstrong@bry.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279434	WELL	PR	08/01/2012	GW	045-11035	CHEVRON 18-344D	PR
279435	WELL	PR	07/10/2006	GW	045-11036	CHEVRON 18-441D	PR
279436	WELL	PR	06/19/2014	GW	045-11037	CHEVRON 18-434D	PR
279437	WELL	PR	04/09/2006	GW	045-11038	CHEVRON 18-444D	PR

General Comment:

I, Inspector Mike Longworth, conducted a routine inspection at BERRY PETROLEUM COMPANY LLC, CHEVRON D20 696, Location 335161 in Garfield County, Colorado.

Location

Lease Road:			
Type	Access		
comment:	Road appears recently maintained.		
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Container label is faded and degraded.		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign not a tank battery.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 2		
Comment:			

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Chemical container at wells.		
Corrective Action:		Date:	
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:	Braden head accessible for monitoring.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	<50 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	500 gallons
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	<100 BBLs	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Comment:							
Corrective Action:						Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS		
CONDENSATE	2	300 BBLs	STEEL AST		,		
Comment:							
Corrective Action:						Date:	

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:						Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 279434 Type: WELL API Number: 045-11035 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 279435 Type: WELL API Number: 045-11036 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 279436 Type: WELL API Number: 045-11037 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Facility ID: 279437 Type: WELL API Number: 045-11038 Status: PR Insp. Status: PR**Producing Well**Comment: [Producing well](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Check Dams	Pass					
Ditches	Pass					
Rip Rap						
		Ditches				
		Rip Rap				
		Culverts				
				Material Handling And Spill Prevention		
Gravel						
Berms	Pass					
		Check Dams				
Compaction						
		Compaction				
		Gravel				
		Berms				

Comment: [Road and storm water BMPs appear recently maintained.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101315	Inspection 701101314 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5385890