

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-68S96W /32SENW

Location ID: 334187



Photo #3262 from entrance to location.



Photo #3263 from entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-68S96W /32SENW

Location ID: 334187



Photo #2364 from inspection #699802188 conducted on 12/2/21.



Photo #3264 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-68S96W /32SENW

Location ID: 334187



Photo #2365 from inspection #699802188 conducted on 12/2/21.



Photo #3265 Location lacks stabilization.

Inspection Photos

Location Name: CAERUS PICEANCE LLC ENCANA-68S96W /32SENW

Location ID: 334187



Photo #2367 from inspection #699802188 conducted on 12/2/21.



Photo #3266 No form of tracking control at entrance to location