

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/24/2021

Submitted Date:

03/24/2021

Document Number:

699802813

FIELD INSPECTION FORMLoc ID 334187 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

17 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
289614	WELL	PR	09/15/2011	GW	077-09248	ENCANA 32-6(F32OU)	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 3/24/21 at approximately 12:00 hours, I, Inspector Corey De Paolo, Conducted a follow up inspection at CAERUS PICEANCE LLC ENCANA-68S96W /32SENW, Location #334187 in Mesa County Colorado.
Refer to document #699802188 inspection conducted on 12/2/20. Not all previous corrective action have been completed.

CAERUS PICEANCE LLC submitted FIR RESOLUTION FORM #402560781 stating that some level of rutting is normal wear and tear during active snow melt/wet conditions. Location and access road are stabilized unpaved surfaces (graveled and compacted) and that the location was bladed.

While there, I observed normal production operations.
During this inspection the following possible compliance issues were observed:

1) Location lacks stabilization. See photo #2364, #3264, #2365 and #3265. No form of tracking control at entrance to location. See photo #2367 and #3266 with a previous corrective action date of 12/17/20.

-Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.
This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:	Note there is no battery sign located at the battery. The previous information was posted on the tanks and does not meet the new battery sign requirements of Rule 605 e.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Sign located at separator and not the wellhead			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	911			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:				
Corrective Action:				Date:
Overall Good: <input checked="" type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	Barbed wire fence			
Corrective Action:				Date:
Equipment:				
Type: Bird Protectors	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 1			
Comment:	All meter runs have been calibrated in the last year.			

Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Summit midstream		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Pressure transducers located on all braden heads. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:	Well on plunger lift		
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	1	1000 GAL	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:	Centralized containment				
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 289614	Type: WELL	API Number: 077-09248	Status: PR	Insp. Status: PR
Producing Well				
Comment:	Producing			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Other	Fail					No form of tracking control
Culverts						
		Culverts				
Compaction	Fail					Location lacks stabilization
		Sediment Traps				
Berms						
		Ditches				
Gravel						By wellhead
		Berms				
Ditches						

Comment: [Location lacks stabilization. See photo #2364, #3264, #2365 and #3265. No form of tracking control at entrance to location. See photo #2367 and #3266](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations.](#)

Date: 12/17/2020

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Storm water for corrective actions.	depaoloc	03/24/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802814	Photos for Insp. #699802813	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5386001