

Inspection Photos
Operator: Logos Operating
Facility: 067-08119
Date: 3/23/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area facing westward from the southern entrance. Revegetation was conducted and is in an early seral vegetative condition. Weed debris not observed.



Photo 3. View of the eastern project area facing northward from the southeastern corner.



Photo 4. View of reference area comprised of sagebrush shrubland with understory of grasses and forbs such as western wheatgrass and James galleta, as well as other dormant species not identified at this time.



Photo 5. View of closed gate after leaving location.