

**Inspection Photos**  
**Operator: Simcoe**  
**Facility: 067-07861**  
**Date: 3/23/2021**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southwestern fill slope facing southeastward from the western corner. Revegetation appears to be progressing in a dormant/grazed condition with crested wheatgrass and western wheatgrass observable.



Photo 3. View of musk thistles at the access road entrance. Approximately 150 musk thistles observed here and along the access road. Inset shows living rosettes.



Photo 4. View of reference area comprised of irrigated grass fields. Grasses are largely dormant at this time and not in identifiable condition.



Photo 5. View of closed gate after leaving location.