

**Inspection Photos**  
**Operator: Simcoe**  
**Facility: 067-09312**  
**Date: 3/23/2021**



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area facing northward from the southeastern corner. Revegetation appears to be progressing in a dormant/grazed condition with crested wheatgrass and western wheatgrass observable.



Photo 3. View of reference area comprised of grass field in a dormant/grazed condition. Perennial grasses are not identifiable at this time.