

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/19/2021

Submitted Date:

03/19/2021

Document Number:

700702449

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
335167 _____ Ramsey, Scott _____ 2A Doc Num: _____

Status Summary:

THIS IS A FOLLOW UP INSPECTION

FOLLOW UP INSPECTION REQUIRED

NO FOLLOW UP INSPECTION REQUIRED

Findings:

11 _____ Number of Comments

2 _____ Number of Corrective Actions

Corrective Action Response Requested

Operator Information:

OGCC Operator Number: 96850

Name of Operator: TEP ROCKY MOUNTAIN LLC

Address: PO BOX 370

City: PARACHUTE State: CO Zip: 81635

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, COGCC		conor.pesicka@state.co.us	
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
283953	WELL	PR	06/10/2009	GW	045-12043	MEAD FEDERAL 30-09D	PR
283954	WELL	PR	04/11/2007	GW	045-12042	MEAD FEDERAL 30-15B	PR
283981	WELL	PR	04/11/2007	GW	045-12056	MEAD FEDERAL 30-10B	PR
283983	WELL	PR	06/10/2009	GW	045-12058	MEAD FEDERAL 30-16D	PR

General Comment:

COGCC Inspection Report Summary
On Thursday 3/18/2021 at approximately 1000, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Mead 30-11, at Location # 335167 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, Black bear, NSO Habitat and Wildlife Management Area.

During this inspection the following possible compliance issues were observed:

1. Tank battery signage does not meet requirements of new rule 605.e
2. Location and lease road show signs of lack of stabilization/compaction.
3. Tracking is evident onto County road 317 (Beaver Creek Road)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:	Location and lease road show signs of lack of stabilization/compaction. Tracking is evident onto County road 317 (Beaver Creek Road)		
Corrective Action:	Maintain vehicle tracking BMPs, control potential sediment discharges from operational roads, well pads, and other unpaved surfaces to comply with rule 1002.f.(2)F.	Date:	03/25/2021

Overall Good:

Signs/Marker:			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Tank battery signage does not meet requirements of new rule 605.e		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:		
Comment:	911	
Corrective Action:		Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 4		
Comment:			

Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	chemical tank at well heads in plastic containment		
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	OTHER	STEEL AST		
Comment:	250 bbl tank				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor		
Comment:			
Corrective Action:			Date:

Inspected Facilities									
Facility ID:	<u>283953</u>	Type:	<u>WELL</u>	API Number:	<u>045-12043</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>283954</u>	Type:	<u>WELL</u>	API Number:	<u>045-12042</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>283981</u>	Type:	<u>WELL</u>	API Number:	<u>045-12056</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				
Facility ID:	<u>283983</u>	Type:	<u>WELL</u>	API Number:	<u>045-12058</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>producing</u>								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts				
Berms		Ditches				
Compaction	Fail	Compaction	Fail			

Comment: This location is within or in close proximity to a CPW Density/High Priority Habitat, Black bear, NSO Habitat and Wildlife Management Area. Location and lease road show signs of lack of stabilization/compaction.

Corrective Action: Install or repair required BMPs

Date: 05/19/2021

Pits: NO SURFACE INDICATION OF PIT

Permit:	Facility ID	Permit Num	Expiration Date
	286379	1433498	

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402634395	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5381565
700702451	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5381560