

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/25/2021

Submitted Date:

03/26/2021

Document Number:

699103302

**FIELD INSPECTION FORM**

Loc ID 434790 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10071

Name of Operator: HIGHPOINT OPERATING CORPORATION

Address: 555 17TH ST STE 3700

City: DENVER State: CO Zip: 80202

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

7 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Frishmuth, Rusty		rfrishmuth@hpres.com	<a href="#">All Inspections</a>
Kraich, Adam		adam.kraich@state.co.us	
Morgan, John		john.morgan@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434789	WELL	TA	07/02/2019	DSPW	123-38343	Anschutz State 5-62-36-12 SWD	TA

**General Comment:**

This was a witness on an MIT. No tubing in well.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 434789 Type: WELL API Number: 123-38343 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: T/A Well MIT no tubing in well:  
MIRU Fluid Energy Services truck, Pressured casing to 340 psig and isolated well bore from truck. Initial Casing @ 340 psig, Initial BH @0 psig. 5 Min Casing @340 psig, 5 min BH @0 psig, 10 Min Casing @340 psig, 10 min BH @0 psig, 15 Min Casing @340 psig, 15 min BH @0 psig. Released pressure, SIW. An extra 4 min. was marked due to the marker not marking on the chart.

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_  
End Surf Csg Pressure: \_\_\_\_\_

Comment: Appears to have no bradenhead test on file perform test and submit reports. 05/07/2021

Corrective Action: Comply with Rule 419 Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Thursday 3/25/21 at approximately 1500hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Anschutz State 5-62-36-12 SWD of HighPoint Operating Corp., at API # 05-123-38343 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issue was observed: Appears to have no bradenhead test on file perform test and submit reports. Comply with Rule 419. With a corrective action date of 5/7/21.</p> <p>At the time of inspection an MIT was performed.</p> <p>T/A Well MIT no tubing in well: MIRU Fluid Energy Services truck, Pressured casing to 340 psig and isolated well bore from truck. Initial Casing @ 340 psig, Initial BH @0 psig. 5 Min Casing @340 psig, 5 min BH @0 psig, 10 Min Casing @340 psig, 10 min BH @0 psig, 15 Min Casing @340 psig, 15 min BH @0 psig. Released pressure, SIW. An extra 4 min. was marked due to the marker not marking on the chart.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	03/26/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
699103303	Inspection Photos	<a href="http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5386636">http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5386636</a>