







40.09888, -108.85679, 5149.9ft, 277°
03/24/2021 11:55:39 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 3. Oil spill originating from flow line next to pump jack.

McLaughlin SR 17
API: 05-103-40158



40.09895, -108.8569, 5138.8ft, 135°
03/24/2021 11:56:29 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 4. Oil spill channel.

McLaughlin SR 17
API: 05-103-40158



40.09921, -108.85677, 5148.0ft, 180°
03/24/2021 12:11:39 PM





40.09916, -108.85684, 5146.3ft, 91°
03/24/2021 12:15:16 PM



40.09912, -108.85585, 5161.5ft, 8°
03/24/2021 11:59:00 AM



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo 7. Tank.

McLaughlin SR 17
API: 05-103-40158

