

Inspection Photos

3/25/2021

Operator: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567

Garfield County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430567



Photo 1: Photo taken from the south end of the Location, facing north. Photos 1-4 show that Pad stabilization concerns remain evident on Location, and appear to have worsened- control measures to stabilize/protect unpaved areas of the Location remain missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430567



Photo 2: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430567



Photo 3: See comments under photo 1.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430567



Photo 4: See comments under photo 1.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567



Photo 5: Photo taken from the north end of the Location. Photo shows that control measures to protect/stabilize the cut slopes on the Location remain missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430567



Photo 6: Photo taken from the north end of the Location. Photo shows that control measures to protect/stabilize the cut slopes on the Location remain missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430567



Photo 7: Photo taken from the north end of the Location. Photo shows that control measures to protect/stabilize the cut slopes on the Location remain missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430567



Photo 8: Photo taken from the north end of the Location. Photo shows that control measures to protect/stabilize the cut slopes on the Location remain missing or insufficient.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430567



Photo 9: Photo taken from the north end of the Location. Photo shows that control measures to protect/stabilize the cut slopes on the Location remain missing or insufficient.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567



Photo 10: Photo taken from the west end of the Location, facing south. Photo shows stormwater run-on ditch has not been installed in accordance with good engineering practices, or maintained in proper functioning condition; stormwater incision within the ditch evident.



Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430567



Photo 11: Photo taken from the west end of the Location. Photo shows stormwater run-on ditch has not been installed in accordance with good engineering practices, or maintained in proper functioning condition; stormwater incision within the ditch evident.

Inspection Photos
Operator Name: TEP ROCKY MOUNTAIN LLC - 96850
Location ID: 430567



Photo 12: Photo taken from the west end of the Location. Photo shows stormwater run-on ditch has not been installed in accordance with good engineering practices, or maintained in proper functioning condition; stormwater incision within the ditch evident.

Inspection Photos

Operator Name: TEP ROCKY MOUNTAIN LLC - 96850

Location ID: 430567



Photo 13: Photo taken from the south end of the tank battery. Photo shows stained soils. Control and contain spills/releases and clean up per Rule 912.a.