



Inspection Photos
Well 081-06588
Spill# 454583
REM #11176
Inspection Date: 3/11/2021
All Photos taken by Kris Neidel

Photo #1 sign at tank battery



Inspection Photos
Well 081-06588
Spill# 454583
REM #11176
Inspection Date: 3/11/2021
All Photos taken by Kris Neidel

Photo #2 stockpiled soil from spill excavation.





Inspection Photos
Well 081-06588
Spill# 454583
REM #11176
Inspection Date: 3/11/2021
All Photos taken by Kris Neidel

Photo #2 same as photo #2





Inspection Photos
Well 081-06588
Spill# 454583
REM #11176
Inspection Date: 3/11/2021
All Photos taken by Kris Neidel

Photo #4. area where flowline failed on right of photo. Contamination also seen under Dehy.





Inspection Photos
Well 081-06588
Spill# 454583
REM #11176
Inspection Date: 3/11/2021
All Photos taken by Kris Neidel

Photo #5 stained soil



Inspection Photos
Well 081-06588
Spill# 454583
REM #11176
Inspection Date: 3/11/2021
All Photos taken by Kris Neidel

Photo #6 It appears there are shallow coal deposits that were exposed.



Inspection Photos
Well 081-06588
Spill# 454583
REM #11176
Inspection Date: 3/11/2021
All Photos taken by Kris Neidel

Photo #7 flowline to wellhead.



Inspection Photos
Well 081-06588
Spill# 454583
REM #11176
Inspection Date: 3/11/2021
All Photos taken by Kris Neidel

Photo #8 stockpiled soil from spill excavation.





Inspection Photos
Well 081-06588
Spill# 454583
REM #11176
Inspection Date: 3/11/2021
All Photos taken by Kris Neidel

Photo #9 looking south

