

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/27/2021

Submitted Date:

03/27/2021

Document Number:

695104187

**FIELD INSPECTION FORM**

Loc ID 333946 Inspector Name: Beardslee, Tom On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 10705  
Name of Operator: EVERGREEN NATURAL RESOURCES LLC  
Address: 1875 LAWRENCE ST STE 1150  
City: DENVER State: CO Zip: 80202

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Distribution, Evergreen		cogcc.evergreen@enrllc.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
268707	WELL	AC	12/18/2011	GW	071-07889	Burson 31-8V	AC
271870	WELL	PR	06/14/2004	GW	071-08039	Burson 31-8R	PR

**General Comment:**

**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Fencing/:**

Type PIT

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Equipment:**

corrective date

Type: Deadman # & Marked # 7

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Vertical Separator # 1

Comment:

Corrective Action:

Date: \_\_\_\_\_

Type: Progressive Cavity # 1

Comment: ELECTRIC DRIVEHEAD

Corrective Action:

Date: \_\_\_\_\_

Type: Ancillary equipment # 3

Comment: TELEMETRY, ELECTRIC DRIVEHEAD AND SEISMIC MONITORING EQUIPMENT

Corrective Action:

Date: \_\_\_\_\_

Type: Gas Meter Run # 2

Comment: BOTH CAL. REPORTS INDICATE GAS METERS HAVE BEEN CALIBRATED WITHIN THE LAST YEAR.

Corrective Action:

Date: \_\_\_\_\_

Type: Bradenhead # 2

Comment: BOTH ARE PLUMBED TO SURFACE

Corrective Action:

Date: \_\_\_\_\_

**Venting:**

Yes/No NO

Comment:

Corrective Action:

Date: \_\_\_\_\_

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 268707 Type: WELL API Number: 071-07889 Status: AC Insp. Status: AC

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SEISMIC MONITOR WELL

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 271870 Type: WELL API Number: 071-08039 Status: PR Insp. Status: PR

**Producing Well**

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Ditches	Pass	Culverts	Pass			
Compaction	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695104188	INSP. PHOTOS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5387269">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5387269</a>