

Inspection Photos

Location Name: CAERUS PICEANCE LLC KNOX-68S96W /14SENW

Location ID: 334083

Network time is not synchronized
Local: Mar 25, 2021 at 12:26:29 PM MDT



Photo #3276 from entrance to location.

Network time is not synchronized
Local: Mar 25, 2021 at 12:26:32 PM MDT



Photo #3277 from entrance to location

Inspection Photos

Location Name: CAERUS PICEANCE LLC KNOX-68S96W /14SEnw

Location ID: 334083



Network: Mar 25, 2021 at 12:54:39 PM MD
Local: Mar 25, 2021 at 12:54:39 PM MD



Network time is not synchronize
Local: Nov 24, 2020 at 1:23:01 PM MS

Photo #3278 Location lacks stabilization.

Photo #2326 from inspection #699802158 conducted on 11/24/20.

Inspection Photos

Location Name: CAERUS PICEANCE LLC KNOX-68S96W /14SENW

Location ID: 334083



Photo #3279 Location lacks stabilization.



Photo #2327 from inspection #699802158 conducted on 11/24/20.

Inspection Photos

Location Name: CAERUS PICEANCE LLC KNOX-68S96W /14SENW

Location ID: 334083



Photo #3280 No form of tracking control at entrance to location



Photo #2325 from inspection #699802158 conducted on 11/24/20.