

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/26/2021

Submitted Date:

03/29/2021

Document Number:

699802832**FIELD INSPECTION FORM**

Loc ID Inspector Name: On-Site Inspection ☐
 423081 De Paolo, Corey 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:22 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423048	WELL	PR	06/07/2012	GW	045-20639	Federal 25-4C (PE-25)	PR
423067	WELL	PR	09/01/2020	GW	045-20652	Federal 25-5B (PE-25)	PR
423069	WELL	PR	11/01/2020	GW	045-20654	Federal 25-4A (PE-25)	PR
423076	WELL	PR	05/13/2012	GW	045-20661	Federal 25-4B (PE-25)	PR
423094	WELL	PR	06/07/2012	GW	045-20670	Federal 25-5C (PE-25)	PR
423096	WELL	PR	04/01/2019	GW	045-20671	Federal 25-5A (PE-25)	PR
423100	WELL	PR	03/01/2019	GW	045-20673	Federal 25-4D (PE-25)	PR
423105	WELL	PR	09/01/2020	GW	045-20677	Federal 25-5D (PE-25)	PR

General Comment:**COGCC Inspection Report Summary**

On Friday 3/26/21 at approximately 13:00 hours, I, Inspector Corey De Paolo,
 Conducted, a follow up inspection at CAERUS PICEANCE LLC FEDERAL-68S95W /7NWNW,
 Location #311684 in Garfield County Colorado.

Refer to document #699802443 inspection conducted on 1/20/21. All previous corrective actions have been completed.

While there, I observed normal production operations.

During this inspection the following possible compliance issues were observed:

1) Location lacks stabilization. See photo #3314 and #3315. No form of tracking control at entrance to location. See photo #3316 with a corrective action date of 4/10/21.

- Location is located in a high priority habitat area.

A follow up on this site inspection needs to be conducted to ensure the
 Compliance issues have been corrected to comply with COGCC rules.
 This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Hog panels		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Hog panels		
Corrective Action:		Date:	

Equipment:				corrective date
Type: Horizontal Heated Separator	# 8			
Comment:				
Corrective Action:				Date:
Type: Gas Meter Run	# 8			
Comment:	All meter runs have been calibrated in the last year.			
Corrective Action:				Date:
Type: Ancillary equipment	# 3			
Comment:	Chemical tanks			
Corrective Action:				Date:
Type: Plunger Lift	# 8			
Comment:	All wells on plunger lift			
Corrective Action:				Date:
Type: Bird Protectors	# 4			
Comment:				
Corrective Action:				Date:
Type: Bradenhead	# 8			
Comment:	Pressure transducers located on all braden heads. All braden head valves are accessible.			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	423048	Type:	WELL	API Number:	045-20639	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	423067	Type:	WELL	API Number:	045-20652	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	423069	Type:	WELL	API Number:	045-20654	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	423076	Type:	WELL	API Number:	045-20661	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	423094	Type:	WELL	API Number:	045-20670	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	423096	Type:	WELL	API Number:	045-20671	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	423100	Type:	WELL	API Number:	045-20673	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	423105	Type:	WELL	API Number:	045-20677	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						By Wellheads
		Compaction				
		Check Dams				
		Gravel				
Compaction	Fail					Location lacks stabilization.
Other	Fail					No form of tracking control
		Culverts				
Berms						
		Sediment Traps				
Sediment Traps						
		Berms				
Ditches						
		Ditches				

Comment: [Location lacks stabilization. See photo #3314 and #3315. No form of tracking control at entrance to location. See photo #3316](#)

Corrective Action: [Oil and gas operators shall implement and maintain Best Management Practices \(BMPs\) at all oil and gas locations.](#)

Date: 04/10/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Refer to Storm water for corrective actions.	depaoloc	03/29/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699802834	Photos for Insp. #699802832	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5387788