Inspector Name: Ramsey, Scott

FORM INSP

> Rev X/20

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109





Inspection Date: 03/25/2021
Submitted Date:

Document Number: 700702478

03/25/2021

FIELD INSPECTION FORM

							<u>700702478</u>			
Loc ID										
334885	Ramsey, Scot	t	2A	Doc Num:		THIS IS A FOLLOW UP I	NSPECTION			
Operator Info	ormation:			×	FOLLOW UP INSPECTION	N REQUIRED				
OGCC Opera	ator Number:	10456				NO FOLLOW UP INSPECTION REQUIRED				
Name of Ope	rator: CAERUS F	PICEANCE	LLC		<u>Fi</u>	Findings:				
Address: 10	 01 17TH STREE1	T #1600				11 Number of Comments				
						3 Number of Corrective Actions				
City:	DENVER	State:	CO	Zip: 802	<u>02</u>	▼ Corrective Action Response Requested				
						ANY CORRECTIVE ACT PREVIOUS INSPECTION BEEN ADDRESSED ARE	IS THÁT HAVE NOT			
Contact Info	rmation:				•					
Contact Nar	ne	Phon	е	Email		Comment				
			COGCC.inspections@caerus oilandgas.com							
Inspected Fa	cilities:									
Facility ID	Туре	Status	Status Date	Well Class	API Num	Facility Name	Insp Status			
211352	WELL	PR	11/10/1997	GW	045-07112	GRAHAM 32-13	PR			
268782	WELL	PR	10/18/2003	GW	045-09295	GRAHAM 32-12C (M	132) PR			
268783	WELL	PR	07/01/2018	GW	045-09296	GRAHAM 32-13D (M	l32) PR			
275355	WELL	SI	01/01/2020	GW	045-13526	GRAHAM 6-8D (M32	e) SI			
General Comment: COGCC Inspection Report Summary On Wednesday 3/24/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus M32, at Location # 334885 in Garfield county Colorado. While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls. During this inspection the following possible compliance issues were observed: 1. Tank battery signage does not meet requirements of new rule 605.e 2. Location and access road show signs of lack of stabilization/compaction 3. Hole in tank containment Refer to photograph of observed compliance issue. A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.										

Inspector Name: Ramsey, Scott

<u>Location</u>							
Lease Road:							
Туре	Access						
comment:							
Corrective ActionL					Date		
Overall Good:							
Signs/Marker:	Signs/Marker:						
Туре	BATTERY						
Comment:	1. Tank battery signage	does not meet	requ	uirements of new rule 605.e			
Corrective Action:	Install sign to comply w	ith Rule 605.e.			Date	: <u>05/25/2021</u>	
Туре	WELLHEAD						
Comment:							
Corrective Action:					Date	:	
Туре	TANK LABELS/PLACA	RDS					
Comment:							
Corrective Action:					Date	:	
Туре	CONTAINERS						
Comment:							
Corrective Action:	Corrective Action:						
Emergency Contact I	Emergency Contact Number:						
Comment:	:: 911						
Corrective Action:					Date		
Good Housekeeping:							
Туре	DEBRIS						
Comment:							
Corrective Action:	Corrective Action:						
Overall Good: 🔀	Overall Good: 🔀						
Spills:							
Туре	Area	Volume					
In Containment: No							
Comment:							
Multilple Spills and Releases?							
Equipment:					corrective date		
Type: Vertical Heated Separator		# 2					
Comment:							
Corrective Action:					Date:		
Type: Ancillary equip	ment	# 1					
Comment	heads in plastic	cont	tainment				
Corrective Action:					Date:		

Inspector Name: Ramsey, Scott # 1 Type: Gas Meter Run Comment: Corrective Action: Date: Type: Bradenhead # 4 Comment: Braden heads have telemetry for monitoring. Corrective Action: Date: Type: Bird Protectors #3 Comment: Corrective Action: Date: Type: Horizontal Heated Separator #2 Comment: Corrective Action: Date: Type: Plunger Lift # 4 Comment: Corrective Action: Date: Tanks and Berms: SE GPS Contents Capacity Type Tank ID CONDENSATE 300 BBLS STEEL AST Comment: Corrective Action: Date: **Paint** Condition | Adequate Other (Content) Other (Capacity) Other (Type) **Berms** Permeability (Wall) Permeability (Base) Maintenance Type Capacity Metal Adequate Walls Insufficient Base Sufficient Inadequate Comment: Hole in tank containment Date: 05/25/2021 Corrective Action: Install liner material to ensure spill or released materials will be maintained with containment structure. Venting: Yes/No NO Comment: Corrective Action: Date: Flaring: Type Comment: Corrective Action: Date:

Inspector Name: Ramsey, Scott									
				Inspected	d Facilities				
Facility ID:	211352	2 Type:	WELL	API Number:	045-07112	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
C	omment:	producing							
Corrective	e Action:							Date:	
Facility ID:	268782	Type:	WELL	API Number:	045-09295	Status: _	PR	Insp. Status:	PR
				Produc	ing Well				
C	omment:	producing							
Corrective	e Action:							Date:	
Facility ID:	268783	Type:	WELL	API Number:	045-09296	Status:	PR	Insp. Status:	PR
				Produc	ing Well				
C	omment:	producing							
Corrective	e Action:							Date:	
Facility ID:	275355	Type:	WELL	API Number:	045-13526	Status:	SI	Insp. Status:	SI
				Idle V	Mall				
Purnos	e: 👿 S	hut In	Temporarily		Reminder:				
•	•			Abandoned					
		last produce	90 1/1/2020						
Correctiv	e Action:							Date:	

Inspector Name: Ramsey, Scott

Reclamation - Storm Water - Pit						
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Fail	Ditches				
		Culverts				
Berms		Compaction	Fail			
Comment:	bear, NSO ha documentation	s within or in close proxing bitat and Wildlife Managen of their Best Managem daccess road show sigr	ement Area. Ope ent Practices for	rator (Caerus) has Sediment Tracking	provided Controls.	
Corrective Action:	tion: Install or repair required BMPs Date: 05/25/2021					

Attached Documents

You can go to COGCC Images (https://cogcc.state.co.us/weblink/) and search by document number:

Document Num	Description	URL
700702484	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5387856

Date Run: 3/29/2021 Doc [#700702478] Page 5 of 5