

Inspection Photos

API: 073-06449

Operator: WIEPKING-FULLERTON ENERGY

Inspection Date: 3/25/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06449 | Date: 3/25/2021

Inspection Photos



Photo 1. Facing east toward the access road near the Bubba State 4 location. A portion of the access road was not regraded and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06449 | Date: 3/25/2021

Inspection Photos



Photo 2. Facing east along the access road. It appears the a portion of the road was recently seeded however, the road is compacted. The road needs to be decompacted and reseeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06449 | Date: 3/25/2021

Inspection Photos



Photo 3. Facing east toward the location. It appears the location have been recently drill seeded.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 073-06449 | Date: 3/25/2021