

# Inspection Photos

API: 073-06513

Operator: WIEPKING-FULLERTON ENERGY

Inspection Date: 3/25/2021



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06513 | Date: 3/25/2021

## Inspection Photos



**Photo 1.** Facing at the fenced location. The fence is not maintained.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06513 | Date: 3/25/2021



## Inspection Photos



**Photo 2.** Center of the location facing north.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06513 | Date: 3/25/2021



## Inspection Photos



**Photo 3.** Center of the location facing west. Areas at the western portion of the location do not appear to be establishing desirable vegetation.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06513 | Date: 3/25/2021



## Inspection Photos



**Photo 4.** View of groundcover at the western side of the location shows mostly undesirable weeds (Kochia).



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06513 | Date: 3/25/2021



## Inspection Photos



**Photo 5.** Facing east at the location. The eastern side of the location consists of desirable vegetation cover which appears to be establishing.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 073-06513 | Date: 3/25/2021