

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2021

Submitted Date:

03/30/2021

Document Number:

699103310

FIELD INSPECTION FORMLoc ID 442279 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

19 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Evins, Bret		bret.evins@state.co.us	
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442262	WELL	PR	11/01/2020	OW	123-41757	Trimar Farms 29T-301	PR
442263	WELL	PR	01/01/2020	OW	123-41758	Trimar Farms 29T-241	PR
442265	WELL	PR	01/01/2020	OW	123-41760	Trimar Farms 29T-401	PR
442267	WELL	PR	01/01/2021	OW	123-41761	Trimar Farms 29Q-321	PR
442268	WELL	PR	01/01/2020	OW	123-41762	Trimar Farms 29Q-221	PR
442271	WELL	PR	01/01/2020	OW	123-41764	Trimar Farms 29T-221	PR
442273	WELL	PR	11/01/2020	OW	123-41766	Trimar Farms 29Y-341	PR
442278	WELL	PR	11/01/2020	OW	123-41767	Trimar Farm 29Y-201	PR

General Comment:

Location

Overall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:	Missing NFPA Placard/ Capacity label on fiberglass pit. See attached photo		
Corrective Action:	Install sign to comply with Rule 605.h.	Date:	05/11/2021
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused Heater hoses in containment with VRU need to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606	Date:	05/11/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	IGNITOR/COMBUSTOR		
Comment:	Panel		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:

Type: Plunger Lift	# 8		corrective date
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 16		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 8		
Comment:	Appear to be plumbed to surface.		
Corrective Action:			Date:
Type: VRU	# 1		
Comment:	Flogistix compressor		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 9		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 8		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:	Shares containment with crude oil tanks. Load out control tank.					
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,	
Comment:	Shares containment with crude oil tanks.					
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		

Other (Capacity) 210 BBL						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	4	OTHER	STEEL AST		40.365800,-104.459500	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity) 538 BBL						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)		Maintenance
Metal	Adequate	Walls Sufficient		Base Sufficient		Adequate
Comment:						
Corrective Action:						Date:
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities

Facility ID: 442262 Type: WELL API Number: 123-41757 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/11/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 45 Fluid Type: _____End Surf Csg Pressure: 45

Comment:

Corrective Action:

Date:

Facility ID: 442263 Type: WELL API Number: 123-41758 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/11/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type: _____End Surf Csg Pressure: 2

Comment:

Corrective Action:

Date:

Facility ID: 442265 Type: WELL API Number: 123-41760 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/11/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: _____End Surf Csg Pressure: 5

Comment:

Corrective Action:

Date:

Facility ID: 442267 Type: WELL API Number: 123-41761 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/11/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type:

End Surf Csg Pressure: 1

Comment:

Corrective Action:

Date:

Facility ID: 442268 Type: WELL API Number: 123-41762 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/11/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type:

End Surf Csg Pressure: 5

Comment:

Corrective Action:

Date:

Facility ID: 442271 Type: WELL API Number: 123-41764 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 04/11/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 2 Fluid Type:

End Surf Csg Pressure: 2

Comment:

Corrective Action:

Date:

Facility ID: 442273 Type: WELL API Number: 123-41766 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 11/27/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 10 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID:	442278	Type:	WELL	API Number:	123-41767	Status:	PR	Insp. Status:	PR
--------------	--------	-------	------	-------------	-----------	---------	----	---------------	----

Producing Well

Comment:	PR	
Corrective Action:		Date:

BradenHead

Date of Last Brhd Test:	04/11/2020	Annual Brhd Completed?	Yes
Last Brhd Test Results	Initial Surf Csg Pressure:	5	Fluid Type:
	End Surf Csg Pressure:	5	
Comment:			
Corrective Action:			Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 3/30/21 at approximately 0806hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Trimar Farms 5N63W29T of PDC Energy, at Location ID # 442279 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Missing NFPA Placard/ Capacity label on fiberglass pit. Install sign to comply with Rule 605.h. With a corrective action date of 5/11/21.</p> <p>Unused Heater hoses in containment with VRU need to be removed for good housekeeping. Comply with Rule 606. With a corrective action date of 5/11/21.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	03/30/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103311	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5389816