

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/30/2021

Submitted Date:

03/30/2021

Document Number:

699103312

FIELD INSPECTION FORM
 Loc ID 442583 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

18 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
Evins, Bret		bret.evins@state.co.us	
,		cogccinspection@pdce.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442584	WELL	PR	11/01/2020	OW	123-41925	R&R Farms 29Q-441	PR
442585	WELL	PR	03/23/2016	OW	123-41926	R&R Farms 29L-201	PR
442586	WELL	PR	11/01/2020	OW	123-41927	R&R Farms 29L-421	PR
442587	WELL	PR	06/01/2020	OW	123-41928	R&R Farms 29L-321	PR
442589	WELL	PR	03/19/2016	OW	123-41930	R&R Farms 29Q-301	PR
443493	WELL	PR	03/18/2016	OW	123-42253	R&R FARMS 29Q-241RD	PR

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment in multiple locations, need to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 606.	Date:	04/08/2021
Type	OTHER		
Comment:	Stained soil from appears to be leaking master valves. See attached photos.		
Corrective Action:	Conduct maintenance on equipment, cleanup stained material and review self-inspection processes per Rule 1002..(2).D	Date:	04/08/2021

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Panel		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: VRU	# 1		
Comment:	Flogistix compressor		
Corrective Action:		Date:	
Type: Other	#		
Comment:	Appears to be leaking Master Valves repair or replace.		
Corrective Action:	Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.		Date: 04/08/2021
Type: Bradenhead	# 6		
Comment:	Appear to be plumbed to surface		
Corrective Action:		Date:	
Type: Bird Protectors	# 13		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 7		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:	Loadout control tank. Shares containment with crude oil tanks.				
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				

Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	FIBERGLASS AST		,	
Comment: Shares containment with crude oil tanks.						
Corrective Action:					Date:	

Paint

Condition						
Other (Content)						
Other (Capacity)	210 BBL					
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	9	OTHER	STEEL AST		40.365900,-104.462900	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate					
Other (Content)						
Other (Capacity)	538 BBL					
Other (Type)						

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	

Venting:

Yes/No	NO						
Comment:							
Corrective Action:						Date:	

Flaring:

Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities

Facility ID: 442584 Type: WELL API Number: 123-41925 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/26/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 442585 Type: WELL API Number: 123-41926 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/26/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 5 Fluid Type: _____End Surf Csg Pressure: 5

Comment:

Corrective Action:

Date:

Facility ID: 442586 Type: WELL API Number: 123-41927 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/26/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 1 Fluid Type: _____End Surf Csg Pressure: 1

Comment:

Corrective Action:

Date:

Facility ID: 442587 Type: WELL API Number: 123-41928 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 04/26/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 442589 Type: WELL API Number: 123-41930 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 04/26/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 15 Fluid Type: _____End Surf Csg Pressure: 15

Comment: _____

Corrective Action: _____

Date: _____

Facility ID: 443493 Type: WELL API Number: 123-42253 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action: _____

Date: _____

BradenHeadDate of Last Brhd Test: 04/26/2020 Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 16 Fluid Type: _____End Surf Csg Pressure: 16

Comment: _____

Corrective Action: _____

Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 3/30/21 at approximately 0858hrs, I, Inspector Adam Burns, Conducted an on-site inspection at R&R Farms 5N63W29Q of PDC Energy, at Location ID # 442583 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment in multiple locations, need to be removed for good housekeeping.</p> <p>Comply with Rule 606. With a corrective action date of 4/8/21.</p> <p>Stained soil from appears to be leaking master valves. Conduct maintenance on equipment, cleanup stained material and review self-inspection processes per Rule 1002..(2).D. With a corrective action date of 4/8/21</p> <p>Appears to be leaking Master Valves repair or replace. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e. With a corrective action date of 4/8/21</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	03/30/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103313	Inspection photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5389817