

**FORM  
INSP**Rev  
X/20

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

03/30/2021

Submitted Date:

03/30/2021

Document Number:

699103314

**FIELD INSPECTION FORM**
 Loc ID 442014 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 69175

Name of Operator: PDC ENERGY INC

Address: 1775 SHERMAN STREET - STE 3000

City: DENVER State: CO Zip: 80203

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

17 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Evins, Bret		bret.evins@state.co.us	
,		cogccinspection@pdce.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
442049	WELL	SI	11/01/2020	OW	123-41633	R&R Farms 29L-441	SI
442050	WELL	SI	03/01/2020	OW	123-41634	R&R Farms 29I-401	SI
442051	WELL	PR	03/22/2016	OW	123-41635	R&R Farms 29L-241	PR
442264	WELL	PR	03/25/2016	OW	123-41759	R&R Farms 29I-221	PR
442432	WELL	SI	01/01/2020	OW	123-41856	R&R Farms 29I-321	PR
442590	WELL	SI	11/01/2020	OW	123-41931	R&R Farms 29L-301	SI

**General Comment:**

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Crude oil tanks that have capacity labels facing south will need to be replaced in the near future due to them being weather. See attached photos.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unused equipment in multiple locations, need to be removed for good housekeeping. See attached photos		
Corrective Action:	Comply with Rule 606.	Date:	04/08/2021

Overall Good: ☐

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Panel		
Corrective Action:		Date:	

**Equipment:**

Type: VRU	# 1		corrective date
Comment:	Flogistix compressor		
Corrective Action:		Date:	

Type: Emission Control Device	# 7		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 6		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 6		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 6		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 6		
Comment:	Appear to be plumbed to surface.		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLS	STEEL AST		,	
Comment:	Loadout control. Shares containment with crude oil tanks.					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:						
Date:						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	PBV FIBERGLASS		,	
Comment:	Shares containment with crude oil tanks.					
Corrective Action:						
Date:						

**Paint**

Condition		
Other (Content)		

Other (Capacity) 210 BBL						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	12	OTHER	STEEL AST		40.366700,-104.469200	
Comment:						
Corrective Action:				Date:		
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity) 538 BBL						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:				Date:		

**Inspected Facilities**

Facility ID: 442049 Type: WELL API Number: 123-41633 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/20/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 20 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 20

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 442050 Type: WELL API Number: 123-41634 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/20/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 32 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 32

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 442051 Type: WELL API Number: 123-41635 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**

Date of Last Brhd Test: 04/20/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 37 Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: 37

Comment: \_\_\_\_\_

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 442264 Type: WELL API Number: 123-41759 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:	Date:
<b><u>BradenHead</u></b>	
Date of Last Brhd Test: <u>04/20/2020</u> Annual Brhd Completed? <u>Yes</u>	
Last Brhd Test Results Initial Surf Csg Pressure: <u>0</u> Fluid Type: _____	
End Surf Csg Pressure: <u>0</u>	
Comment: _____	
Corrective Action: _____	Date: _____

Facility ID: <u>442432</u>	Type: <u>WELL</u>	API Number: <u>123-41856</u>	Status: <u>SI</u>	Insp. Status: <u>PR</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

<b><u>Producing Well</u></b>	
Comment: <u>PR</u>	
Corrective Action: _____	Date: _____

<b><u>BradenHead</u></b>	
Date of Last Brhd Test: <u>04/20/2020</u> Annual Brhd Completed? <u>Yes</u>	
Last Brhd Test Results Initial Surf Csg Pressure: <u>9</u> Fluid Type: _____	
End Surf Csg Pressure: <u>9</u>	
Comment: _____	
Corrective Action: _____	Date: _____

Facility ID: <u>442590</u>	Type: <u>WELL</u>	API Number: <u>123-41931</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
----------------------------	-------------------	------------------------------	-------------------	-------------------------

<b><u>Idle Well</u></b>	
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____	
Comment: <u>SI</u>	
Corrective Action: _____	Date: _____

<b><u>BradenHead</u></b>	
Date of Last Brhd Test: <u>04/20/2020</u> Annual Brhd Completed? <u>Yes</u>	
Last Brhd Test Results Initial Surf Csg Pressure: <u>5</u> Fluid Type: _____	
End Surf Csg Pressure: <u>5</u>	
Comment: _____	
Corrective Action: _____	Date: _____

<b><u>COGCC Comments</u></b>

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 3/30/21 at approximately 1027hrs, I, Inspector Adam Burns, Conducted an on-site inspection at R&amp;R Farms 5N63W29L of PDC Energy, at Location ID # 442014 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused equipment in multiple locations, need to be removed for good housekeeping.</p> <p>Comply with Rule 606. With a corrective action date of 4/8/21.</p> <p>Crude oil tanks that have capacity labels facing south will need to be replaced in the near future due to them being weather.</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	03/30/2021

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699103315	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5389818">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5389818</a>