

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2021

Submitted Date:

03/30/2021

Document Number:

701101336

FIELD INSPECTION FORM
 Loc ID 335577 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

8 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
282342	WELL	PR	03/01/2019	GW	045-11742	CHEVRON 2B-4D	PR
282343	WELL	PR	03/01/2019	GW	045-11741	CHEVRON 2A-4D	PR
282345	WELL	PR	03/01/2019	GW	045-11740	CHEVRON 8B-5D	PR
282349	WELL	SI	04/01/2020	GW	045-11737	CHEVRON 8C-5D	SI
282353	WELL	SI	10/01/2020	GW	045-11734	CHEVRON 2C-4D	SI
282354	WELL	SI	09/01/2019	GW	045-11749	CHEVRON 2E-4D	SI
282355	WELL	PR	03/01/2019	GW	045-11733	CHEVRON 2D-4D	PR

General Comment:

COGCC Inspection Report Summary

I, Inspector Mike Longworth, conducted a follow up inspection at CAERUS PICEANCE LLC, CHEVRON-66S96W 4SWNW, Location # 335578 in

Garfield County, Colorado.

Storm water repairs addressed.

Location**Lease Road:**

Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☐**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:

Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	400 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	300 BBLs	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate

Inspected Facilities				
Facility ID: 282342	Type: WELL	API Number: 045-11742	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:			Date:	
Facility ID: 282343	Type: WELL	API Number: 045-11741	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:			Date:	
Facility ID: 282345	Type: WELL	API Number: 045-11740	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:			Date:	
Facility ID: 282349	Type: WELL	API Number: 045-11737	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment:				
Corrective Action:			Date:	
Facility ID: 282353	Type: WELL	API Number: 045-11734	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment:				
Corrective Action:			Date:	
Facility ID: 282354	Type: WELL	API Number: 045-11749	Status: SI	Insp. Status: SI
Idle Well				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____				
Comment:				
Corrective Action:			Date:	
Facility ID: 282355	Type: WELL	API Number: 045-11733	Status: PR	Insp. Status: PR
Producing Well				
Comment: Producing well				
Corrective Action:			Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Compaction						
		Gravel				
Ditches	Pass					
		Compaction				
		Culverts				
Gravel						
		Check Dams				
		Ditches				
		Gravel				

Comment: Culverts on main road have been repaired and road elevated were crossing those culverts. Outlets at those culverts have been repaired and armed with rock rip rap. Road blade and ditches groomed on main road.

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101337	Inspection 701101336 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5390539