

Inspection Photos
Operator: Simcoe
Facility: 067-07558
Date: 3/29/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing, largely with smooth brome and mixed wheatgrasses.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of the reference area comprised of irrigated grass field comprised largely of smooth brome and mowed grasses not identifiable at this time.