

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2021

Submitted Date:

03/30/2021

Document Number:

695104227

FIELD INSPECTION FORMLoc ID 322278 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 17210

Name of Operator: CINNAMON CREEK OIL & GAS INC

Address: P O BOX 544

City: WALSH State: CO Zip: 81090

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	
Duran, Alicia		alicia.duran@state.co.us	
Hasty, Tim	(719) 429-3529/ (719) 340-0329	thhasty@gmail.com	All Inspections
Mills, Rick	719-324- 5630/719-353- 2523	rickmills000@gmail.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
210101	WELL	PR	02/01/2021	OW	043-40038	SPANGLER 1	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	PHOTO 3: SEVERAL PIECES OF TRASH TROUGHOUT LOCATION. PHOTO 4: ANOTHER EXAMPLE OF TRASH AROUND LOCATION.		
Corrective Action:	REMOVE ALL TRASH, rubbish, and other waste materials, COMPLY WITH RULE 606.D.	Date:	04/13/2021
Type	UNUSED EQUIPMENT		
Comment:	PHOTO 5: UNUSED EQUIPMENT LEFT ON LOCATION (2" PIPE AND BOARDS). PHOTO 7: UNUSED EQUIPMENT LEFT ON LOCATION (55 GAL. DRUM AND SHOVEL). PHOTO 6: UNUSED EQUIPMENT LEFT ON LOCATION (RED HOSE).		
Corrective Action:	REMOVE ALL UNUSED EQUIPMENT FROM LOCATION, COMPLY WITH RULE 606.D.	Date:	04/13/2021

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Pump Jack	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	ELECTRIC EQUIPMENT		
Corrective Action:		Date:	
Type: Horizontal Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	2	200 BBLS	STEEL AST		,	
Comment:	PHOTO 8: BOTH CRUDE OIL TANK ARE OPEN TO THE ATMOSPHERE THERE ARE NO GAUGE HATCHES ON EITHER TANK.					
Corrective Action:	INSTALL GAUGE HATCHES ON CRUDE OIL TANKS AND OPERATE per Rule 608.a.(9).					Date: 04/30/2021

Paint

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No		
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities				
Facility ID: 210101	Type: WELL	API Number: 043-40038	Status: PR	Insp. Status: PR
Producing Well				
Comment:				
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
695104228	INSP. PHOTOS	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5390765