

## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /18SWNE

Location ID: 334316



**Photo #3356 from entrance to location.**



**Photo #3357 Access road lacks stabilization.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /18SWNE

Location ID: 334316



**Photo #3358 Access road lacks stabilization.**



**Photo #3360 Access road lacks stabilization.**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /18SWNE

Location ID: 334316



**Photo #3359 Sediment has migrated into ditch**



**Photo #3361 Sediment has migrated into ditch**



## Inspection Photos

Location Name: CAERUS PICEANCE LLC KEINATH FEDERAL-68S96W /18SWNE

Location ID: 334316



**Photo #3362** No form of tracking control at entrance to access road.



**Photo #3363** Access road is used to access location and does not have any public access.