

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

12/01/2020

Document Number:

402543214

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 10633 Contact Person: Schuyler Hamilton
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (303) 774-4017
Address: 1801 CALIFORNIA STREET #2500 Email: Schuyler.Hamilton@Crestonepr.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes ☒ No ☐

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 332706 Location Type: Production Facilities
Name: MANTLE-64N65W Number: 28SWNE
County: WELD
Qtr Qtr: SWNE Section: 28 Township: 4N Range: 65W Meridian: 6
Latitude: 40.285480 Longitude: -104.664640

Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

This form is submitted as a December 1, 2020 update including a description of corrosion protection, integrity management system and GIS data.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 456906 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 332220 Location Type: Well Site ☐
Name: MANTLE-64N65W Number: 28SWNE
County: WELD No Location ID
Qtr Qtr: SWNE Section: 28 Township: 4N Range: 65W Meridian: 6
Latitude: 40.284556 Longitude: -104.666607
Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Max Outer Diameter:(Inches) 3.000
Bedding Material: Date Construction Completed: 04/05/2004
Maximum Anticipated Operating Pressure (PSI): Testing PSI:
Test Date:

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 10/15/2018

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

Flowline was disconnected from wellhead and from separator. 835' of flowline was abandoned in place. Both ends plugged below ground. Flowline was flushed with 25bbls fresh water prior to plugging. Flowline was verified free of hydro carbons with LEL monitor. Flowline was cut below ground level. Flowline was capped on both ends with 120lbs of slurry per state NTO, then backfilled on both ends.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 473075 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 328934 Location Type: Well Site ☐
Name: OSTER-64N65W Number: 28NWNE
County: WELD No Location ID
Qtr Qtr: NWNE Section: 28 Township: 4N Range: 65W Meridian: 6
Latitude: 40.288346 Longitude: -104.666497
Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Date Construction Completed: 04/16/1993
Maximum Anticipated Operating Pressure (PSI): Testing PSI:
Test Date:

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: _____

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

OPERATOR COMMENTS AND SUBMITTAL

Comments This form is submitted as a December 1, 2020 update including a description of corrosion protection, integrity management system and GIS data.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 12/01/2020 Email: Schuyler.Hamilton@Crestonepr.com

Print Name: Schuyler Hamilton Title: EHS Field Tech

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:  _____ Director of COGCC Date: 3/31/2021

Conditions of Approval

COA Type

Description

Attachment Check List

Att Doc Num

Name

402543214	Form44 Submitted
402543270	OFF-LOCATION FLOWLINE GEODATABASE GDB
402643311	OFF-LOCATION FLOWLINE GIS GDB

Total Attach: 3 Files

Data retrieval failed for the subreport 'GeneralComment' located at: \\DNR\WBP004\eFormReports\General_Cmt.rdlc. Plea