

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



OGCC RECEPTION

Receive Date:

12/01/2020

Document Number:

402543963

Off-Location Flowline

The Flowline Report, Form 44, shall be submitted to register, report realignment, report removal from service, provide pre-abandonment notices, or report abandonment of Off-Location Flowlines, Flowline Systems, Produced Water Transfer Systems, or Crude Oil Transfer Lines or Systems as required by the 1100 Series Rules. The Form 44 shall also be submitted to register, report realignment, or report abandonment of Domestic Taps, and to report Grade 1 Gas Leaks from Flowlines per Rules 610 and 906.

Operator Information

OGCC Operator Number: 10633 Contact Person: Schuyler Hamilton
Company Name: CRESTONE PEAK RESOURCES OPERATING LLC Phone: (303) 774-4017
Address: 1801 CALIFORNIA STREET #2500 Email: Schuyler.Hamilton@Crestonepr.com
City: DENVER State: CO Zip: 80202
Is the Operator a Tier One member of the Utility Notification Center of Colorado (CO811) that participates in Colorado's One Call notification system? Yes No

OFF LOCATION FLOWLINE

FLOWLINE ENDPOINT LOCATION IDENTIFICATION

Location ID: 429489 Location Type: Production Facilities
Name: ECHEVERRIA 62N67W Number: 2/NENW BATTERY
County: WELD
Qtr Qtr: NENW Section: 2 Township: 2N Range: 67W Meridian: 6
Latitude: 40.170940 Longitude: -104.861760

Description of Corrosion Protection

Crestone pipelines are covered in a protective external coating. Flowlines are subject to thorough inspections and fabrication standards during installation to minimize coating and pipe defects. Crestone maintains a chemical program to reduce internal corrosion. If a flowline is found to lack integrity, Crestone will investigate, report, and remediate any spills in accordance with the 900 series rules.

Description of Integrity Management Program

Crestone flowlines are pressure tested prior to placing flowlines into service. Flowlines are tested on an annual basis in accordance with COGCC 1104 series rules. If a flowline is found to lack integrity, Crestone will investigate the root cause, as well as report and remediate any spills in accordance with the 900 series rules. All repairs will be completed in accordance with COGCC 1102 Series rules.

Description of the construction method used for public by-ways, road crossings, sensitive wildlife habitats, sensitive areas, and natural and manmade watercourses (i.e., open trench, bored and cased, or bored only), if applicable.

N/A

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 465550 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 330769 Location Type: Well Site
Name: ECHEVERRIA Number: 0-2-2
County: WELD No Location ID
Qtr Qtr: NENW Section: 2 Township: 2N Range: 67W Meridian: 6
Latitude: 40.171960 Longitude: -104.860180
Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 3.000
Bedding Material: _____ Date Construction Completed: 06/03/1998
Maximum Anticipated Operating Pressure (PSI): _____ Testing PSI: _____
Test Date: _____

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 08/15/2019

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

Flowline was disconnected from separator and from well. Flowline was flushed with 25bbls fresh water prior to abandonment. Verified with LEL monitor that line was free of hydrocarbons. Flowline was plugged on both ends with 120lbs of slurry per State NTO.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 465552 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 330769 Location Type: Well Site
Name: ECHEVERRIA Number: 0-2-2
County: WELD No Location ID
Qtr Qtr: NENW Section: 2 Township: 2N Range: 67W Meridian: 6
Latitude: 40.171960 Longitude: -104.860180
Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 3.000
Bedding Material: _____ Date Construction Completed: 02/15/2013
Maximum Anticipated Operating Pressure (PSI): _____ Testing PSI: _____
Test Date: _____

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 08/15/2019

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

Flowline was disconnected from separator and from well. Flowline was flushed with 25bbls fresh water prior to abandonment. Verified with LEL monitor that line was free of hydrocarbons. Flowline was plugged on both ends with 120lbs of slurry per State NTO.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 473048 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 429488 Location Type: Well Site
Name: ECHEVERRIA 62N67W Number: 2/NENW HZ PAD
County: WELD No Location ID
Qtr Qtr: NENW Section: 2 Township: 2N Range: 67W Meridian: 6
Latitude: 40.172930 Longitude: -104.861750

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: Date Construction Completed: 02/14/2013
Maximum Anticipated Operating Pressure (PSI): Testing PSI:
Test Date:

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date:

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 465549 Flowline Type: Wellhead Line Action Type:

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 330937 Location Type: Well Site
Name: ECHEVERRIA-62N67W Number: 2SEW
County: WELD No Location ID
Qtr Qtr: SENW Section: 2 Township: 2N Range: 67W Meridian: 6
Latitude: 40.168277 Longitude: -104.859572

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 3.000
Bedding Material: _____ Date Construction Completed: 03/22/2001
Maximum Anticipated Operating Pressure (PSI): _____ Testing PSI: _____
Test Date: _____

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 08/15/2019

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

Flowline was disconnected from separator and from well. Flowline was flushed with 25bbls fresh water prior to abandonment. Verified with LEL monitor that line was free of hydrocarbons. Flowline was plugged on both ends with 120lbs of slurry per State NTO.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 465551 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 330769 Location Type: Well Site
Name: ECHEVERRIA Number: 0-2-2
County: WELD No Location ID
Qtr Qtr: NENW Section: 2 Township: 2N Range: 67W Meridian: 6
Latitude: 40.171960 Longitude: -104.860180

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 3.000
Bedding Material: _____ Date Construction Completed: 02/15/2013
Maximum Anticipated Operating Pressure (PSI): _____ Testing PSI: _____
Test Date: _____

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: 08/15/2019

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

Flowline was disconnected from separator and Crestone well. Flowline was flushed with 25bbls fresh water prior to abandonment. Verified with LEL monitor that line was free of hydrocarbons. Flowline was plugged on both ends with 120lbs of slurry per State NTO.

FLOWLINE FACILITY INFORMATION

Flowline Facility ID: 473047 Flowline Type: Wellhead Line Action Type: _____

OFF LOCATION FLOWLINE REGISTRATION

Equipment at End Point Riser: Separator

Flowline Start Point Location Identification

Location ID: 429488 Location Type: Well Site
Name: ECHEVERRIA 62N67W Number: 2/NENW HZ PAD
County: WELD No Location ID
Qtr Qtr: NENW Section: 2 Township: 2N Range: 67W Meridian: 6
Latitude: 40.172930 Longitude: -104.861750

Equipment at Start Point Riser: Well

Flowline Description and Testing

Type of Fluid Transferred: Multiphase Pipe Material: Carbon Steel Max Outer Diameter:(Inches) 2.000
Bedding Material: _____ Date Construction Completed: 02/14/2013
Maximum Anticipated Operating Pressure (PSI): _____ Testing PSI: _____
Test Date: _____

OFF LOCATION FLOWLINE Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification

Date: _____

Description of Realignment, Out of Service, Pre-Abandonment Notice, or Abandonment Verification:

OPERATOR COMMENTS AND SUBMITTAL

Comments This form is submitted as a December 1, 2020 update including a description of corrosion protection, integrity management system and GIS data.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct and complete.

Signed: _____ Date: 12/01/2020 Email: Schuyler.Hamilton@Crestonepr.com

Print Name: Schuyler Hamilton Title: EHS Field Tech

Based on the information provided herein, this Flowline Report complies with COGCC Rules and applicable orders and is hereby approved.

COGCC Approved:  Director of COGCC Date: 3/31/2021

Conditions of Approval

COA Type

Description

--	--

Attachment Check List

Att Doc Num

Name

402543963	Form44 Submitted
402543970	OFF-LOCATION FLOWLINE GEODATABASE GDB
402643424	OFF-LOCATION FLOWLINE GIS GDB

Total Attach: 3 Files

Data retrieval failed for the subreport 'GeneralComment' located at: \\DNR\WP004\eFormReports\General_Cmt.rdlc. Plea...