

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/31/2021

Submitted Date:

03/31/2021

Document Number:

700702495

FIELD INSPECTION FORMLoc ID 334856 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, COGCC		conor.pesicka@state.co.us	
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211296	WELL	SI	02/01/2020	GW	045-07055	COUEY 32-14	SI
269303	WELL	PR	02/25/2004	GW	045-09345	YEAKEK 32-15C (N32)	PR
269304	WELL	PR	02/19/2004	GW	045-09344	YEAKEK 32-14D (N32)	PR
269306	WELL	PR	07/01/2018	GW	045-09343	SHIDELER 32-11C (N32)	PR

General Comment:**COGCC Inspection Report Summary**

On Tuesday 3/30/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a follow up inspection at Caerus N32, at Location # 334856 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat and Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls. Some of the C/A's from previous inspection document # 700702475 have not been completed, see compliance dates below. A follow up inspection for the C/A not completed will be done on or around said date. Gravel has been added to entrance of access road from CR 315, approx. 90 feet long, 50 foot wide and 3 to 4 inches deep. Lease road has been graded. All inventory of location remains the same as previous inspection. During this inspection the following possible compliance issues were observed:

1. Tank battery signage does not meet requirements of new rule 605.e (5/25/21)
2. Location still shows signs of lack of stabilization/compaction (3/29/21)
3. Four (4) dead men still improperly marked (5/25/21)

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Inspected Facilities

Facility ID: <u>211296</u>	Type: <u>WELL</u>	API Number: <u>045-07055</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>269303</u>	Type: <u>WELL</u>	API Number: <u>045-09345</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>269304</u>	Type: <u>WELL</u>	API Number: <u>045-09344</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>
Facility ID: <u>269306</u>	Type: <u>WELL</u>	API Number: <u>045-09343</u>	Status: <u>PR</u>	Insp. Status: <u>PR</u>

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700702504	photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391865