

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/31/2021

Submitted Date:

04/01/2021

Document Number:

701101345

FIELD INSPECTION FORMLoc ID 335793 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10456

Name of Operator: CAERUS PICEANCE LLC

Address: 1001 17TH STREET #1600

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

1 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
, Caerus Piceance		COGCC.inspections@caerus oilandgas.com	Piceance inspections only

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265284	WELL	PR	03/01/2019	GW	045-08993	CHEVRON 12-17D	PR
265285	WELL	PR	04/01/2019	GW	045-08994	CHEVRON 14-17D	PR
265286	WELL	PR	03/01/2019	GW	045-08995	CHEVRON 13-17D	PR

General Comment:

Follow up Inspection Report

Follow up to 8/2021 inspection # 701101237

Storm water BMPs repairs have been addressed on location and access road from main road to location. Culvert on main road is in process of being cleaned out.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Location

Lease Road:			
Type	Main		
comment:	Continue routine maintance.		
Corrective Action	L	Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	911		
Corrective Action:		Date:	

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

<u>Venting:</u>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	
<u>Flaring:</u>			
Type			
Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 265284 Type: WELL API Number: 045-08993 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 265285 Type: WELL API Number: 045-08994 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Facility ID: 265286 Type: WELL API Number: 045-08995 Status: PR Insp. Status: PR**Producing Well**Comment: Producing well

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Gravel						
Compaction						
		Culverts	Fail			Culvert on main road repair in process.
Ditches	Pass					
		Rip Rap	Pass			
Berms	Pass					
		Berms	Pass			
		Culverts	Pass			
		Ditches	Pass			

Comment: Storm water BMPs have been repaired on location and access road from main road to location. Culvert on main road repair in process.

Corrective Action: Install or repair required BMPs per Rule 1002.f.(2)C

Date: 03/23/2021

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701101346	Inspection 701101345 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391980