

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/31/2021

Submitted Date:

04/01/2021

Document Number:

701500144

**FIELD INSPECTION FORM**Loc ID 316280 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 200502

Name of Operator: 31 OPERATING

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

9 Number of Comments

4 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Boulger, Levin		lboulger@31operating.com	
Ikenouye, Teri		teri.ikenouye@state.co.us	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
260295	WELL	SI	10/01/2020	GW	103-10144	ANT HILL UNIT 36-12	SI

**General Comment:**

A follow up inspection of documents

- 1) FIR 700701076 dated 12-28-2020.

The following compliance issues are uncompleted:

- 1) Debris on location. Photos 3 to 5. Complete by 2-1-2021.

Additional compliance issues:

- 1) Missing "911" on battery sign. Photo 6. Complete by 6-1-2021.
- 2) Erosion channel on edge of location. Photos 7 & 8. Complete by 6-1-2021.
- 3) Production history not current. Complete by 5-1-2021.

Location is with a CDPHE Reg 42 Limited use & quality area, Rule 1202.c Aquatic sportfish management waters, Rule 1202.d Mule deer severe winter range area, Rule 1202.d Mule deer winter concentration area, and Rule 309.e.1 Greater sage grouse general habitat management area.

This is a summary of inspection report 701500144.

### Location

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign at meter building.		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Missing "911" on battery sign.

Corrective Action: Install sign to comply with Rule 605.d.

Date: 06/01/2021

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Debris on location.		
Corrective Action:	Remove debris.	Date:	02/01/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead access present.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		

Comment: <a href="#">Chemical container.</a>		Date:
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment: <a href="#">Telemetry.</a>		Date:
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:		Date:
Corrective Action:		Date:
Type: Plunger Lift	# 1	
Comment:		Date:
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLS	STEEL AST		,
Comment:					Date:
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					Date:
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				Date:
Corrective Action:				Date:



**Inspected Facilities**Facility ID: 260295 Type: WELL API Number: 103-10144 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last reported monthly operations were January 2021. Production is missing for July 2020 to September 2020. Most recent reported production April 2020. Report past due monthly operations.

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.b.

Date: 05/01/2021

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel				Material Handling And Spill Prevention		
Ditches						
Berms						

Comment: [Stormwater channels running off edge of location and rutting on location.](#)

Corrective Action: [Install, maintain, or provide documentation of post construction management plan or BMP's.](#)

Date: 06/01/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500145	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5392389">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5392389</a>