

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/31/2021

Submitted Date:

04/02/2021

Document Number:

696202529

FIELD INSPECTION FORM

 Loc ID 422990 Inspector Name: Trujillo, Aaron On-Site Inspection 2A Doc Num:
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 77330
 Name of Operator: SG INTERESTS I LTD
 Address: 100 WAUGH DR SUITE 400
 City: HOUSTON State: TX Zip: 77007
Findings:

- 2 Number of Comments
 1 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
 PREVIOUS INSPECTIONS THAT HAVE NOT
 BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
, SG Interests		inspection@sginterests.com	
Arthur, Denise		denise.arthur@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
422990	LOCATION	AC			-	HL 11-89-19 1	RI

General Comment:

On 3/31/2021, Reclamation Specialist Trujillo conducted an interim reclamation and stormwater inspection at SG Interests' HL 11-89-19 #1 location in Gunnison County, Colorado.

This inspection is a followup to inspection #696201322, #696201671 and #696202025 to document compliance with the following corrective actions:
 1002.f: Stormwater

It was observed in this inspection that the Location remains out of compliance with COGCC Rules and corrective actions.

Refer to the "Stormwater" section of this inspection report for additional details.

Refer to the photo-documentation of the observed compliance issues attached to this report.

Any corrective action(s) from previous inspections that have not been addressed are still applicable.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

Inspected Facilities

Facility ID: 422990 Type: LOCATION API Number: - Status: AC Insp. Status: RI

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Previous inspection documented that control measures to stabilize and protect the Location were missing or insufficient. Inspections required Operator to comply with Rule 1002.f.(2)C.

It was observed in this inspection that BMPs to stabilize and protect slopes remain missing or insufficient. It was also observed that the slope drains have not been constructed with an appropriate outlet in accordance with good engineering practices.

This corrective action has not been addressed and remains applicable.

Corrective Action: Install or repair required BMPs in accordance with good engineering practices per Rule 1002.f.(2)C.

Date: 06/13/2020

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696202530	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5393074