

Inspection Photos

API: 071-09582

Operator: OGRIS OPERATING LLC

Inspection Date: 4/1/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09582 | Date: 4/1/2021

Inspection Photos



Photo 1. Facing toward the access road. The access road is rutted and not stabilized and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09582 | Date: 4/1/2021

Inspection Photos



Photo 2. Facing toward the location. There is no secondary containment around the PW tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09582 | Date: 4/1/2021

Inspection Photos



Photo 3. The well sign is faded and not legible.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09582 | Date: 4/1/2021

Inspection Photos



Photo 4. There appears to be oil stained soil near the well.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09582 | Date: 4/1/2021