

Inspection Photos
Suckla-Brown Unit 17 Header
Spill ID 478370 (AC)



Photo 1 – Open spill excavation; impacted soils appear to still be in place in excavation wall adjacent to header. Hydrocarbon sheen visible on groundwater in excavation.



Photo 2 – Impacted soils appear to still be in place in excavation wall adjacent to header. Hydrocarbon sheen visible on groundwater in excavation.

Inspection Photos
Suckla-Brown Unit 17 Header
Spill ID 478370 (AC)



Photo 3 – Soil stockpiled on site with no BMPs



Photo 4 – Fencing around open excavation