

Inspection Photos

API: 071-09475

Operator: OGRIS OPERATING LLC

Inspection Date: 4/1/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-09475 | Date: 4/1/2021

Inspection Photos



Photo 1. Facing west along the main road at Lat/Long:37.1099,-104.94878. Erosion has occurred along the fill slope of the road. This area needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09475 | Date: 4/1/2021

Inspection Photos



Photo 2. Facing along the main road. It appears vehicles slipped off the road causing rutting. The road needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09475 | Date: 4/1/2021

Inspection Photos



Photo 3. Facing toward the access road at right side of photo. There is rutting along the main road ascending the hill which needs to be repaired and stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09475 | Date: 4/1/2021

Inspection Photos



Photo 4. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09475 | Date: 4/1/2021

Inspection Photos



Photo 5. There is vehicle rutting on the location. The fence around the pit needs to be repaired to prevent wildlife entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-09475 | Date: 4/1/2021