

Inspection Photos

API: 071-07944

Operator: OGRIS OPERATING LLC

Inspection Date: 4/1/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 071-07944 | Date: 4/1/2021

Inspection Photos



Photo 1. Facing west toward the access road at the canyon bottom near AC 1-16. The road in the canyon bottom is rutting and not maintained or stabilized.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07944 | Date: 4/1/2021

Inspection Photos



Photo 2. It appears a vehicle slid off the road and got stuck which has caused ruts off the road.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07944 | Date: 4/1/2021

Inspection Photos



Photo 3. The road along the canyon bottom is not stabilized and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07944 | Date: 4/1/2021

Inspection Photos



Photo 4. The road along the canyon bottom is not stabilized and maintained.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07944 | Date: 4/1/2021

Inspection Photos



Photo 5. Facing toward the access road to the right which leads to the location.



Inspection Photos



Photo 6. Facing toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 071-07944 | Date: 4/1/2021