

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

03/30/2021

Submitted Date:

03/30/2021

Document Number:

695104227

FIELD INSPECTION FORMLoc ID 322278 Inspector Name: Beardslee, Tom On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 17210

Name of Operator: CINNAMON CREEK OIL & GAS INC

Address: P O BOX 544

City: WALSH State: CO Zip: 81090

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|------------------|-----------------------------------|-----------------------------|-----------------|
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Duran, Alicia | | alicia.duran@state.co.us | |
| Hasty, Tim | (719) 429-3529/ (719) 340-0329 | thhasty@gmail.com | All Inspections |
| Mills, Rick | 719-324- 5630/719-353- 2523 | rickmills000@gmail.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 210101 | WELL | PR | 02/01/2021 | OW | 043-40038 | SPANGLER 1 | PR |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|---|-------|------------|
| Type | TRASH | | |
| Comment: | PHOTO 3: SEVERAL PIECES OF TRASH TROUGHOUT LOCATION. PHOTO 4: ANOTHER EXAMPLE OF TRASH AROUND LOCATION. | | |
| Corrective Action: | REMOVE ALL TRASH, rubbish, and other waste materials, COMPLY WITH RULE 606.D. | Date: | 04/13/2021 |
| Type | UNUSED EQUIPMENT | | |
| Comment: | PHOTO 5: UNUSED EQUIPMENT LEFT ON LOCATION (2" PIPE AND BOARDS). PHOTO 7: UNUSED EQUIPMENT LEFT ON LOCATION (55 GAL. DRUM AND SHOVEL). PHOTO 6: UNUSED EQUIPMENT LEFT ON LOCATION (RED HOSE). | | |
| Corrective Action: | REMOVE ALL UNUSED EQUIPMENT FROM LOCATION, COMPLY WITH RULE 606.D. | Date: | 04/13/2021 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|----------------------------|--------------------|-------|-----------------|
| Type: Pump Jack | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Ancillary equipment | # 1 | | |
| Comment: | ELECTRIC EQUIPMENT | | |
| Corrective Action: | | Date: | |
| Type: Horizontal Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| | | | | | |
|--------------------|--|----------|-----------|---------|------------------|
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| CRUDE OIL | 2 | 200 BBLS | STEEL AST | | , |
| Comment: | PHOTO 8: BOTH CRUDE OIL TANK ARE OPEN TO THE ATMOSPHERE THERE ARE NO GUAGE HATCHES ON EITHER TANK. | | | | |
| Corrective Action: | INSTALL GUAGE HATCHES ON CRUDE OIL TANKS AND OPERATE per Rule 608.a.(9). | | | | Date: 04/30/2021 |

Paint

| | |
|-----------|----------|
| Condition | Adequate |
|-----------|----------|

| | |
|------------------|--|
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| | | | | |
|--------------------|----------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|--|-------|
| Yes/No | | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 210101 | Type: | WELL | API Number: | 043-40038 | Status: | PR | Insp. Status: | PR |
| Producing Well | | | | | | | | | |
| Comment: | | | | | | | | | |
| Corrective Action: | | | | Date: | | | | | |

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms | Pass | | | | | |
| Compaction | Pass | Compaction | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 402644506 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5390773 |
| 695104228 | INSP. PHOTOS | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5390765 |