

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2021

Submitted Date:

03/31/2021

Document Number:

701002668

**FIELD INSPECTION FORM**

Loc ID 320989 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Operator Information:**

OGCC Operator Number: 76175  
Name of Operator: SANDLIN OIL CORP  
Address: 1580 LINCOLN ST SUITE 580  
City: DENVER State: CO Zip: 80203

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

- 14 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Sandlin, Gary		SandlinOilCorporation@gmail.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
205691	WELL	SI	05/01/2020	GW	009-06102	RD JONES 1	SI

**General Comment:**

[Routine Inspection](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Two track through CRP		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign is laying on the ground and needs installed		
Corrective Action:	Install lease sign		Date: 04/30/2021
Type	TANK LABELS/PLACARDS		
Comment:	No labeling on tank		
Corrective Action:	Install sign to comply with Rule 605.h.		Date: 04/30/2021
Emergency Contact Number:			
Comment:	<input style="width: 100%;" type="text"/>		
Corrective Action:	<input style="width: 100%;" type="text"/>		Date: _____
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:	<input style="width: 100%;" type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	LOCATION		
Comment:	Fencing may be necessary around location. CRP is actively being grazed with livestock		
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Prime Mover	# 1		corrective date
Comment:	Arrow gas engine		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Gas scrubber		
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:	Meter run is 1.25 miles North of wellhead by county road 53		
Corrective Action:			Date:
Type: Vertical Separator	# 1		
Comment:	Vertical gas separator on east side of water tank		
Corrective Action:			Date:

Type: Pump Jack	# 1	
Comment:	Lufkin model 9	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	200 BBLs	Open Top		37.174550,-102.108670
Comment:	Fiberglass open top water tank				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Berms are inadequate			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 912.d.(1).			Date: 04/30/2021

**Venting:**

Yes/No	
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 205691 Type: WELL API Number: 009-06102 Status: SI Insp. Status: SI

**Producing Well**

Comment: Producing. Casing production. Meter run is 1.25 miles north of wellhead by county road 53

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Other	Pass			

Comment: [Access is grassed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402645526	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391694">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391694</a>
701002675	location photo	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391688">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391688</a>