

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

03/30/2021

Submitted Date:

03/31/2021

Document Number:

701002670

**FIELD INSPECTION FORM**

Loc ID 321173 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 76175  
Name of Operator: SANDLIN OIL CORP  
Address: 1580 LINCOLN ST SUITE 580  
City: DENVER State: CO Zip: 80203

**Findings:**

- 12 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name   | Phone | Email                           | Comment |
|----------------|-------|---------------------------------|---------|
| Sandlin, Gary  |       | SandlinOilCorporation@gmail.com |         |
| Pesicka, Conor |       | conor.pesicka@state.co.us       |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 259738      | WELL | PR     | 04/01/2019  | GW         | 009-06617 | HEIRONIMUS 1  | PR          |

**General Comment:**

[Routine Inspection](#)

| Location   |  |        |                 |
|--|--|--------|-----------------|
| <b>Lease Road:</b>                                     |  |        |                 |
| Type   | Access   |        |                 |
| comment:   | Access to wellhead is farmed over                |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Overall Good: <input checked="" type="checkbox"/>      |  |        |                 |
| <b>Signs/Marker:</b>                                   |  |        |                 |
| Type   | WELLHEAD   |        |                 |
| Comment:   | Lease sign by water tank                         |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type   | TANK LABELS/PLACARDS                             |        |                 |
| Comment:   | Sticker on tank                                  |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Emergency Contact Number:                              |  |        |                 |
| Comment:   |  |        |                 |
| Corrective Action:                                     |  |        | Date: _____     |
| <b>Good Housekeeping:</b>                              |  |        |                 |
| Type   | UNUSED EQUIPMENT                                 |        |                 |
| Comment:   | VGS laying on the ground next to unit            |        |                 |
| Corrective Action:                                     | Remove unused equipment from location            | Date:  | 06/30/2021      |
| Overall Good: <input checked="" type="checkbox"/>      |  |        |                 |
| <b>Spills:</b>   |  |        |                 |
| Type   | Area   | Volume |                 |
| In Containment: No                                     |  |        |                 |
| Comment:   |  |        |                 |
| <input type="checkbox"/> Multiple Spills and Releases? |  |        |                 |
| <b>Equipment:</b>                                      |  |        |                 |
| Type: Vertical Separator                               | # 1  |        | corrective date |
| Comment:   | Vertical gas separator on south side of wellhead |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type: Gas Meter Run                                    | # 1  |        |                 |
| Comment:   | Meter shed is 1800' SW of wellhead               |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type: Prime Mover                                      | # 1  |        |                 |
| Comment:   | Arrow gas engine                                 |        |                 |
| Corrective Action:                                     |  | Date:  |                 |
| Type: Pump Jack  | # 1  |        |                 |
| Comment:   | Parkersburg unit                                 |        |                 |
| Corrective Action:                                     |  | Date:  |                 |

| <b>Tanks and Berms:</b>   |            |                     |                     |             |                       |
|---|------------|---------------------|---------------------|-------------|-----------------------|
| Contents  | #          | Capacity            | Type                | Tank ID     | SE GPS                |
| PRODUCED WATER  | 1          | OTHER               | FIBERGLASS AST      |             | 37.181830,-102.126820 |
| Comment:  |            |                     |                     |             |                       |
| Corrective Action:  |            |                     |                     |             | Date:                 |
| <b>Paint</b>  |            |                     |                     |             |                       |
| Condition:  |            |                     |                     |             |                       |
| Other (Content):  |            |                     |                     |             |                       |
| Other (Capacity): 150bbbs   |            |                     |                     |             |                       |
| Other (Type):   |            |                     |                     |             |                       |
| <b>Berms</b>  |            |                     |                     |             |                       |
| Type  | Capacity   | Permeability (Wall) | Permeability (Base) | Maintenance |                       |
| Earth   | Inadequate | Walls Insufficient  | Base Insufficient   | Inadequate  |                       |
| Comment: Berms are inadequate   |            |                     |                     |             |                       |
| Corrective Action: Repair or install berms or other secondary containment devices per Rule 912.d.(1). |            |                     |                     |             | Date: 04/30/2021      |
| <b>Venting:</b>   |            |                     |                     |             |                       |
| Yes/No:   |            |                     |                     |             |                       |
| Comment:  |            |                     |                     |             |                       |
| Corrective Action:  |            |                     |                     |             | Date:                 |
| <b>Flaring:</b>   |            |                     |                     |             |                       |
| Type:   |            |                     |                     |             |                       |
| Comment:  |            |                     |                     |             |                       |
| Corrective Action:  |            |                     |                     |             | Date:                 |

**Inspected Facilities**

Facility ID: 259738 Type: WELL API Number: 009-06617 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Central meter run for \(Heironimous 1 & Leach 1\) 1800' SW](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

|                  |                 |                         |                       |               |                          |         |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Other            | Pass            | Other                   | Pass                  |               |                          |         |

Comment: [Location and access are farmed over](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description          | URL   |
|--------------|----------------------|---|
| 402645528    | INSPECTION SUBMITTED | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391696">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391696</a> |
| 701002674    | location photo       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391690">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391690</a> |