

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/05/2021

Submitted Date:

04/07/2021

Document Number:

693802921

FIELD INSPECTION FORM

Loc ID 323895 Inspector Name: BROWNING, CHUCK On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|---------------------------------|-----------------|
| Browning, Chuck | 970-433-4139 | chuck.browning@state.co.us | Field Inspector |
| Labowskie, Steve | | steve.labowskie@state.co.us | |
| Contact, General | | regulatory@foundationenergy.com | All inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 211115 | WELL | SI | 06/01/2020 | GW | 045-06874 | GOVT. 14-2 | SI |

General Comment:

COGCC staff performed a routine field inspection on 4/5/2021.
No issues were found. See inspection text and photos for details.

Location

| | | | |
|--------------------|--------|--|-------|
| Lease Road: | | | |
| Type | Main | | |
| comment: | | | |
| Corrective Action | | | Date: |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |

Overall Good:

| | | | |
|----------------------|-----------------------|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Sign at tank battery. | | |
| Corrective Action: | | | Date: |

| | | | |
|---------------------------|-----------------------|--|-------------|
| Emergency Contact Number: | | | |
| Comment: | 1-866-767-3600 or 911 | | |
| Corrective Action: | | | Date: _____ |

Overall Good:

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

Multiple Spills and Releases?

| | | | |
|--------------------|------------------|--|-------|
| Fencing/: | | | |
| Type | SEPARATOR | | |
| Comment: | Hogwire & t-post | | |
| Corrective Action: | | | Date: |
| Type | TANK BATTERY | | |
| Comment: | Hogwire & t-post | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Hogwire & t-post | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------------|-----|--|-----------------|
| Equipment: | | | corrective date |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

| | | | |
|-----------------------------------|-----|--|-------|
| Type: Horizontal Heated Separator | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| PRODUCED WATER | 1 | 200 BBLs | STEEL AST | | 39.392760,-108.962489 |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

Venting:

| | | |
|--------------------|----|-------|
| Yes/No | NO | |
| Comment: | | |
| Corrective Action: | | Date: |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected Facilities

Facility ID: 211115 Type: WELL API Number: 045-06874 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|--|--------------------------|------------------------------------|
| Compaction | Pass | Compaction | Pass | Material Handling And Spill Prevention | Pass | Secondary containment of chemicals |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------------|---|
| 693802933 | Insoection photos 4/5/2021 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5397567 |