

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

04/06/2021

Submitted Date:

04/07/2021

Document Number:

701500214

**FIELD INSPECTION FORM**Loc ID 314833 Inspector Name: Moran, Rick On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 200502

Name of Operator: 31 OPERATING

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

8 Number of Comments

4 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Ikenouye, Teri		teri.ikenouye@state.co.us	
Thompson, Bud		BLThomps@BLM.gov	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Freeman, Kris	254-717-0435	kfreeman@31operating.com	
Boulger, Levin		lboulger@31operating.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
229692	WELL	SI	10/01/2020	GW	103-07349	FEDERAL 1	SI

**General Comment:**

A routine inspection identified the following compliance issues:

- 1) Missing "911" on battery sign. Photo 4. Complete by 6-7-2021.
- 2) Stormwater channel on location edge. Photos 5 & 6. Complete by 6-7-2021.
- 3) Debris on location. Photos 1, 2, 6. Complete by 4-23-2021.
- 4) Production history not current. Complete by 5-7-2021.

Location is within a Rule 1202.d Mule deer severe winter range area, Rule 1202.d Mule deer winter concentration area, and Rule 309.e.1 Greater sage grouse general habitat management area.

This is a summary of inspection report 701500214.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Sign at meter building.		
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Missing "911" on battery sign.

Corrective Action: Install sign to comply with Rule 605.e.

Date: 06/07/2021

**Good Housekeeping:**

Type	DEBRIS		
Comment:	Debris on location.		
Corrective Action:	Remove debris.	Date:	04/23/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	Telemetry.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Bradenhead access present.		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		

Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 229692 Type: WELL API Number: 103-07349 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: \_\_\_\_\_

Comment: Last reported monthly operations were January 2021. Production is missing for July 2020 to September 2020. Most recent reported production June 2020. Report past due monthly operations.

Corrective Action: Submit required Form 7(s) to COGCC per rule 413.b.

Date: 05/07/2021

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel						
Berms						

Comment: [Stormwater channels on edge of location with sediment choking vegetation.](#)

Corrective Action: [Install, maintain, or provide documentation of post construction management plan or BMP's.](#)

Date: 06/07/2021

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701500215	inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5397631">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5397631</a>