

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

04/01/2021

Submitted Date:

04/01/2021

Document Number:

699103324

FIELD INSPECTION FORM

Loc ID: 434077 Inspector Name: Burns, Adam On-Site Inspection: 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10071
Name of Operator: HIGHPOINT OPERATING CORPORATION
Address: 555 17TH ST STE 3700
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

- 14 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Paben, Brett		bpaben@hpres.com	All Inspections
Kraich, Adam		adam.kraich@state.co.us	
Neighbors, Cory		cneighbors@hpres.com	All Inspections
Frishmuth, Rusty		rfrishmuth@hpres.com	All Inspections
Reese, Jason		jreese@hpres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434059	WELL	PR	07/01/2019	OW	123-37921	70 Ranch 4-63-03-3225CH	PR
434067	WELL	PR	07/01/2019	OW	123-37925	70 Ranch 4-63-3-4956CH	PR
434077	LOCATION	AC			-	70 Ranch 4-63-3 Pad 2	AC
434078	WELL	PR	07/01/2019	OW	123-37930	70 Ranch 4-63-03-3340CH	PR
434079	WELL	PR	07/01/2019	OW	123-37931	70 Ranch 4-63-03-3225CDH	SI
434161	WELL	PR	07/01/2019	OW	123-37993	70 Ranch 4-63-3-4841CH	PR
434162	WELL	PR	07/01/2019	OW	123-37994	70 Ranch 4-63-3-4856CDH	PR

General Comment:

Location

Overall Good:

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	OTHER		
Comment:	Riser next to the compressor discharge line is not Marked or LO/TO. See attached photos.		
Corrective Action:	Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b.	Date:	04/12/2021

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 434059 Type: WELL API Number: 123-37921 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/24/2020 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 434067 Type: WELL API Number: 123-37925 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/24/2020 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 434077 Type: LOCATION API Number: - Status: AC Insp. Status: AC

Producing Well

Comment: AC
 Corrective Action: _____ Date: _____

Facility ID: 434078 Type: WELL API Number: 123-37930 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/24/2020 Annual Brhd Completed? Yes
 Last Brhd Test Results Initial Surf Csg Pressure: 15 Fluid Type: _____
 End Surf Csg Pressure: 0
 Comment: _____
 Corrective Action: _____ Date: _____

Facility ID: 434079 Type: WELL API Number: 123-37931 Status: PR Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: SI at the separator.

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/24/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 434161 Type: WELL API Number: 123-37993 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/24/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

Facility ID: 434162 Type: WELL API Number: 123-37994 Status: PR Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: _____ Date: _____

BradenHead

Date of Last Brhd Test: 08/24/2020 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: _____

End Surf Csg Pressure: 0

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Thursday 4/1/21 at approximately 0900hrs, I, Inspector Adam Burns, Conducted an on-site inspection at 70 Ranch 4-63-3 Pad 2 of HighPoint Operating Corp., at Location ID # 434077 in Weld County, Colorado. During this inspection the following possible compliance issues were observed: Riser next to the compressor discharge line is not Marked or LO/TO. Upon removing a flowline or crude oil transfer line from use with the intent to abandon, an operator must immediately apply OOSLAT to the risers. OOSLAT must stay in place at all times during the process of abandoning the flowline or crude oil transfer line until the operator removes the riser. Comply with Rule 1105.b. With a corrective action date of 4/12/21. See attached photos. A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p>	burnsa	04/01/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402645891	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391983
699103327	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5391977